

0122

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/School/NDZ/2025/ 538

Dated: 20/06/2025

To

The Principal,
St. Marks Sr. Sec. Public School,
Lal Mandir Road, Harsh Vihar, Delhi-110093.

Sub: Regarding Fire Safety Certificate in r/o St. Marks Sr. Sec. Public School, Lal Mandir Road, Harsh Vihar, Delhi-110093

Sir,

This has reference to email dated 02/June/2025 on the subject cited above. In this regard, it is to inform you that the premises was inspected by the officer concerned of this department on 12/06/2025 in the presence of Smt. Suman Singh (Principal) and observed that at present school is comprised of Ground plus three upper floors only. Fire safety measures were checked as per the rules and following shortcomings were observed.

1. Hose Reel Hose provided but nonfunctional.
2. Fire pump of 220 LPM provided against requirement of 450 LPM.
3. Overhead tank of 5,000 ltr capacity provided against requirement of 10,000 ltr.
4. Exit Signage found removed.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangement shall be at the risk and liability of the management. The Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully


(ATUL GARG)

DIRECTOR

DELHI FIRE SERVICE

Copy to:-



1. The Dy. Director of Education, B-Block, Yamuna Vihar, Delhi-110053.