



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

75
आज़ादी का
अमृत महोत्सव

No. F6/DFS/MS/NDZ/2026/ 536

Dated:- 02/06/2026

To,

The Principal,
Sumit Public School,
Gali No. 02, Opposite Shiv Mandir ,
Alipur, Delhi- 110036.

Sub.:- Regarding issuance of Fire Safety Certificate in respect of Sumit Public School, Gali No. 02, Opposite Shiv Mandir, Alipur, Delhi- 110036

Sir,


This has reference to email received from vksainirs16@gmail.com dated 24/04/2026 on the subject cited above. In this connection, it is to inform you that the said building was re-inspected by the officer concerned of this department on 14/05/2026 in the presence of Ms. Saroj (Principal), to check the compliance of shortcomings issued by this department vide letter no. F6/DFS/MS/2013/School/2166 dated 05/09/2013. (Copy enclosed)

During inspection, it has been observed that the shortcomings issued by this department vide above said letter has not been rectified yet.

In view of the above, the application for issuance of Fire Safety Certificate cannot be considered at this stage & rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing Authority/statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

Enclosed: - As above


01/06/26

S.K. Dua
Chief Fire Officer
Delhi Fire Service

Copy to:-

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi – 110054.

C/8

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

NO. F-6/DFS/MS/2013/ school / 2166

Date: 05/08/2013

To

The Principal,
Sumit Public School,
Gali No. 02, Opposite Shiv Mandir,
Alipur, Delhi.

Sub: - Regarding fire safety certificate in respect of Sumit Public School, Gali No. 02, Opposite Shiv Mandir, Alipur, Delhi.


Sir,

Please refer to your letter No Nil Dated 11/07/2013 on the subject cited above. In this connection it is to inform you that the inspection of the above said premises was carried out by the officer concerned of this department along with school authority on 31/07/2013 from fire safety point of view and following shortcomings were observed.

1. The width of staircase is only 110 to 120 cms against required width of 1.5 mtr. The width of staircase is required to be increased to 1.5 mtr or a second staircase with clear width of 0.75 mtr is to be provided.
2. Class room door width is 90-92 cms against the required one mtr width in each class room.

Keeping in view of the above fire safety certificate cannot be considered at this stage. You are requested to provide the fire safety arrangements as per the Circular of Director of Education, issued vide letter no. F6/Estt/CC/FS/11/3298-3398 dated 01/03/2011.

Yours faithfully


(VIPIN KENTAL)
Dy Chief Fire Officer
Delhi Fire Service
Ph: 011-23846352
dcfowz.dlfire@nic.in

Copy to: Director of Education, Old Sectt. Delhi for information

