**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001** 

No: F.6/DFS/MS/Buisness/2025/SZ/ 43 %

To,

Sh. Anil Sawhney (General Secretary), M/s. Suneja Tower- I, Plot No. 7, District Centre, Janakpuri, New Delhi- 58.

Sub:- Regarding renewal of FSC in r/o M/s Suneja Tower- I, Plot No. 7, District Centre, Janak Puri, New Delhi- 110058

Sir,

This has reference to your letter No. Nil, dated 29.07.2025, on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the premises/building on dated 18.08.2025 to verify the fire safety arrangements in accordance with the rules. At the time of inspection Sh. Bhagat (Care-taker), was present and it was observed that the building comprised of basement, ground plus six upper floors, and have following shortcomings were observed:

- 1. Fire Check Doors found removed from main staircase.
- 2. Lift Lobby is not properly segregated.
- 3. Smoke management system found not functional in basement.
- 4. First aid hose reel provided but found not functional.
- 5. Hydrant system provided but found not functional.
- 6. Smoke/Heat detectors provided but found not functional.
- Sprinkler found removed in basement area.
- 8. Underground pumps provided as per requirements but found not functional.
- 9. Exit Sign's found removed at some places.
- 10. The electric wires are found not fixed properly and its going through passage and may cause fire hazard.
- 11. External unit of AC should be removed for the passage.

In view of the above shortcomings, the application for renewal of Fire Safety Certificate is rejected. You are requested to rectify the above-mentioned shortcomings under intimation to this department for taking further necessary action in this matter. Yours faithfully

(Virendra Singh) Chief Fire Officer

The Chairman, DDA, Vikas Sadan, INA, New Delhi- 110003. Copy to: -

The Executive Engineer (Bldg.), MCD, Civic Centre, Minto Road, New Delhi.