

dm

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/School/NDZ/2025/ 274

Dated: 23/04/2025

To

The Principal,
Suthre Shah Public School,
2217, Yamuna Bazar, Delhi - 110006.

Sub: Regarding issuance of Fire Safety Certificate (FSC) in r/o **Suthre Shah Public School** located at **2217, Yamuna Bazar, Delhi - 110006.**

Sir,

This has reference to your letter outdoor diary No. 46 dated 01.04.2025 received in this department on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on dated 17.04.2025 in presence of Mr. Mahant Vivek Shah and observed that the shortcomings intimated vide letter No.F6/DFS/MS/School/2014/814 dated 01/04/2014 (copy enclosed) have not been complied yet.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management.

Yours faithfully,

Encl: As above.

(Atul Garg)

Director ok

Delhi Fire Service

Tel: 011-23414000

42- 21/4 19/11

Copy to:-

The Director of Education,
Govt. of NCT of Delhi, Old Secretariat, Delhi.

c/23

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE**

NEW DELHI- 110001

Ph - 23412025 Email - dcfondz.dfire@nltc.in

No. F6/DFS/MS/school/2014/814

Dated: 01/04/14

To,

The Head Mistress,

Suthre Shah Public School,

Yamuna Bazar, Delhi-110006.

**Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o :
Suthre Shah Public School, Yamuna Bazar, Delhi-110006.**

Madam,

Please refer to your letter No. Nil dated 9.03.14 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school to verify the fire safety arrangements in accordance with the circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.11 issued by the Director of Education. At the time of inspection Smt. Sushma(Head Mistress) was present.

It was observed that the school building comprises of ground plus three upper floors and school is running on second floor only whereas ground floor hall is used for religious purpose and first & third floor are laying vaccant. Fire fighting systems such as fire extinguishers and fire buckets were found provided and following shortcomings were observed :-

1. A hose reel of 30 meters length fitted with 5mm shut-off nozzle on each floor not provided.
2. A fire pump of 450 LPM capacity (40 meters head) on terrace not provided.
3. 10000 liters overhead tank exclusively for firefighting systems at terrace not provided.
4. Exit signage not provided at all exits and escape routes at appropriate locations.

In view of above, the issuance of fire safety certificate cannot be considered at this stage.

Yours faithfully

Copy to:-

The Director of Education,

North Delhi Municipal Corporation,

Dr. SPM Civic Centre, JLN Marg, N.D


(Rajesh Panwar)

Dy. Chief Fire Officer

o/c
ke