




**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**



No.F.6/DFS/MS/Hospital/2025/NDZ/ 1434

Dated: 19/08/2025

To,

Dr. Kusum Arora, Medical Superintendent-Nursing Home
Directorate of Health Services
M.O. I/C Nursing Home Cell, 3rd floor,
Delhi Govt. Dispensary Building, S-1, School Block,
Shakarpur, Delhi-110092.

**Subject:-Regarding issuance of Fire Safety Certificate in r/o Surya Hospital Located at
383/11-C, Azad Nagar, Delhi-110051.**

Sir,

This is in reference to your letter No. F.24/168/SHD/DGHS/NHC/2025/493 dated 10/07/2025 on the subject cited above. In this connection, it is to inform you that officer concerned of this department has visited the Hospital on dated 31/07/2025 in presence of Mr. Sanjay and observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/2018/4589 dated 01/11/2018 (copy enclosed) have not been complied yet.

In view of the above, Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings communicated vide above mentioned letter under intimation to this office for further action.

Yours faithfully,

(VIRENDRA SINGH)

CHIEF FIRE OFFICER

Encl. As above

Copy to:-

The Authorized Signatory, Surya Hospital at 383/11-C, Azad Nagar, Delhi-110051

45
C-47
C/49

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110001

No. fb/dfs/ms/228/4589

Dated: 1/11/18

To,

Dr. S.N. Mishra,
Surya Hospital 383/11-C,
Azad Nagar, Krishna, Delhi-51.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o
Surya Hospital 383/11-C, Azad Nagar, Krishna, Delhi-51.

Sir,


Please refer to your letter no.nil dated 29/08/18 on the subject cited above. In this connection this is to inform you that the officer concerned of this department inspected the Hospital on 20/09/18 to verify the fire safety arrangements in accordance with the rules. At the time of inspection Dr. S.N. Mishra was present and it was observed that the Hospital building is comprised of basement, ground plus three upper floors and have following of shortcomings.

1. An additional staircase width of 2.0 m shall be required at ground to terrace.
2. Main pump having capacity of 1620 LPM output, standby pump 1620 LPM output and jockey pump 180 LPM 40 M head not provided
3. Fire pump capacity of 220 LPM provided in place of 900 LPM at terrace.
4. Over Head water tank capacity of 5,000 Liters provided in place of 10,000 Liters.

In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully

11/11/18
(Vipin Kental)
Chief Fire Officer



Copy to:-

1. The Directorate of Health Services,
M.O. I/C Nursing Home Cell,
Govt. of NCT of Delhi, F-17, Karkardooma, Delhi-32.