GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001

No.F.6/DFS/MS/School/2025/SZ/ 191

Dated: 24/02/2025

FIRE SAFETY CERTIFICATE

Certified that the Sushil International School at Hans Nagar, Pandwala Village, New Delhi110043, comprised of basement (sealed), ground floor plus two upper floors, owned/occupied by
Sushil International School, was issued Fire Safety Certificate by this department vide letter no.
F.6/DFS/MS/School/2022/SZ/198 dated 23.02.2022. The School building was re-inspected by the
officer concerned of this department on 17.02.2025 in the presence of Mr. Manjeet Singh Solanki, and
found that School building have deemed complied the fire prevention and fire safety requirements in
accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for
occupancy class "Educational" w.e.f. 24 o2 2025 for a period of three years in accordance with
Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of
the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 24 o2 2025 at New Delhi by.

Director Delhi Fire Service

Copy to: -

1. The Executive Engineer (Bldg.), MCD, Civic Centre, New Delhi: - for information regarding use of basement.

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

3. The Principal, Sushil International School at Hans Nagar, Pandwala Village, New Delhi- 43.

Conditions for the validity of fire safety certificate: -

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws. Presently basement is sealed by owner.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTIÓN REPORT

1. Name & address of the building

Sushil International School, Hans Nagar, Pandwala Village, New Delhi

2. Building comprised of

Basement (sealed), Ground plus two upper floors.

3. Type of Occupancy

Educational

4. Type of Case

: Renewal

5. Details of Previous NOC

: F.6/DFS/MS/School/2022/SZ/198 dated 23.02.2022

6. Fire Safety directives letter No

N/A

7. Date of inspection

17.02.2025

8. Name of Inspecting Officer

A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side

Sh. Manjeet Singh Solanki

10. Year of Construction

: 2014

11. Applicant's letter No.

S/2024-25/23 dated 28.01.2025

S. No.		um Standards on fire prevention e safety U/R 33	Requirement	Provided at site	Remarks MR/NMR		
	Access	to building					
		Road width	Accessible 06 m	Provided	M/R		
		Gate width	4.5 m	5.3 m.	MR		
		Width of internal road	NA	NA	NA		
2.	Numbe	er, Width, Type & Arrangement of	Exits				
	a. Nun	ber of staircases					
	•	Upper Floors	03 No's	Provided	M/R		
	•	Basements	03 No's	Provided	M/R		
	b. Wid	th of staircases	35 1.0 5				
	•	Upper Floor	1.50 m	1.50 m each	M/R		
	•	Basements	1.50 m	1.50 m each			
	c. Prote	ection of exits	1.30 m	1.50 m each	M/R		
	•	Fire check door	1020 720 725				
		Pressurization	Required	Provided	M/R		
			N/A	N/A	N/A		
	d. No.	of continuous staircases to	Required	One	MR		
	terra		1.50 m	The state of the s	The States		
		th of Corridor	1.50 m	1.55 m	M/R		
		r Size	1.0 m	1.0 m including frame (Double door)	M/R, students are less than 45 in each clas room, old case		
•	Compa	tmentation	•				
	•	Fire check door	N/A	N/A	N/A		
	•	Sealing of electrical shafts	N/A	N/A	N/A		
		Fire Rating of shaft door	N/A	N/A	N/A		
	•	Water Curtain	N/A	N/A	N/A		
	•	Fire Dampers	N/A	N/A	N/A		
	Smoke Management System						
	•	Basements	N/A	N/A	N/A		
	•	Jpper floor	Required	Natural Ventilation	M/R		
	Fire Extinguishers						
		Total numbers	12 no's	Provided	M/R		
		Types	ABC/CO₂ type	Provided	M/R		
	•	S marking	ISI marked	ISI marked	M/R		
×	First-Aid Hose Reels						
	• 1	otal numbers on each floor	One	Provided	M/R		
	• [ength of hose reel hose	30 m	Provided			
		lozzle diameter	05 mm	Provided	M/R M/R		
				de la companya del companya de la companya del companya de la comp	IVIIK		

1	172 500
	172
	10

	Automotive	NIZ			
•	Automatic fire detection and alarming s	ystem			
	Type of detectors	N/A	N/A	N/A	
	Location of Main Panel	N/A N/A	N/A	N/A	
	Location of Repeater Panel	N/A	N/A	N/A	
		N/A	N/A	N/A	
	 Alternate source of power Hooters' Location 	N/A	N/A	N/A	
8.	MOEFA	N/A	N/A	N/A	
9.	Public Address System	N/A	N/A	N/A	
10.	Automatic Sprinkler System				
10.		Required	Provided	M/R	
	Basement	N/A	N/A	N/A	
	 Ground Floor Sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants				
11.	ACCOUNTY TO A CONTROL OF THE CONTROL	N/A	N/A	N/A	
	Size of riser/down-comer	N/A N/A	N/A	N/A	
	 Number of hydrants per floor Hose Box 	N/A	N/A	N/A	
4.5	30 (5-030000) (5-03000	, t			
12.	Yard Hydrants	37/4	N/A	N/A	
	Total number of hydrants	N/A N/A	N/A	N/A	
	Hose Box				
13.	Pumping Arrangements				
	Ground Level	27/4	N/A	N/A	
	Discharge of main Pump	N/A	N/A	N/A	
	➤ Head of Main pump	N/A	N/A	N/A	
	> Number of main pumps	N/A	N/A	N/A	
	> Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump headStandby Pump out put	N/A	N/A	N/A	
E	TId	N/A	N/A	N/A	
	 Standby Pump Head Auto Starting/Manual Stopping 	N/A	N/A	N/A	
		N/A N/A	N/A	N/A	
	> Pump House Access	IVA			
	Terrace level Discharge of nump	450 LPM (02 no.'s)	Provided	M/R	
	> Discharge of pump	430 LFM (02 no. s)	Provided	M/R	
	➤ Head of the pump➤ Power Supply	Required	Provided	M/R	
	➤ Power Supply ➤ Auto Starting of pump	Required	Provided	M/R	
14.	Captive Water Storage for fire fighting				
14.		N/A	N/A	N/A	
	 Underground tank capacity Draw-off connection 	N/A	N/A	N/A	
	> Fire service inlet	N/A	Provided	N/A	
	> Access to tank	N/A	N/A	N/A	
	Overhead Tank capacity	15,000 ltrs.	Provided	M/R	
5	Exit Signage.	Required	Provided	M/R	
5.		required	1 TOVIGEG	WIK	
6.	Provision of Lifts.		(No I	Lift)	
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	N/A	N/A	N/A	
	Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
	Standby power supply	N/A	N/A	1	
	120 • • • 171 •		IN/A	N/A	

53/2

8.	Refuge	Area.				
	>	Total Area	N/A	N/A	N/A	
	>	ocation	N/A	N/A	N/A	
19.	Fire Control Room					
	•	Detector System Panel	N/A	N/A	N/A	
		low Switch Panel	N/A	N/A	N/A	
	•]	A System Panel	N/A	N/A	N/A	
		Battery backup	N/A	N/A	N/A	
		Building Floor Plans	N/A	N/A	N/A	
20.	Special Protecti	Fire Protection System for on of special Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules the FSC issued vide letter number F.6/DF\$/MS/School/2022/SZ/198 dated 23.02.2022, renewal under rule 37, of the Delhi Fire Service Rules 2010 is recommended.

Note: - As per undertaking given by school management (placed at C-41) the school building comprised of basement, ground plus three upper floors. Basement is sealed by owner and not use for any purpose. School running at ground plus two upper floors only.

Signature of Inspecting

Name: - R.K. Yadav Designation: - ADO (JKP)

eften a put up for sign place