## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001 Dated: 08 01 20

No F 6/DFS/MS/GH/2025/NDZ/ 12

## FIRE SAFETY CERTIFICATE

Certified that the "Suzi International" Guest House located at 8483, Arya Nagar, Pahar Ganj, Delhi-110055 comprised of Ground Floor(01 Guest Room + Reception + 01 Office), 1st floor to 3rd floor (06 Guest rooms at each floor) & 4th floor (Closed) was issued FSC by this department vide letter No F6/DFS/MS/GH/NDZ/2021/547 dated 29.12.2021. Owner has submitted an affidavit dated 02.01.2025 regarding not to use any floor above 3<sup>rd</sup> floor. The premise was re-inspected by the officer concerned of this department on 30.12.2024 in the presence of Sh. Naveen Pathak and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have therefore deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise is fit for occupancy "Class A, Residential (Guest House for total 19 Guest Rooms from Ground floor to 3rd floor only)" with effect from ... 08 01 2025. And valid up to 31.03.2027 in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ..... 08 of 2025. at New Delhi, by

Delhi Fire Service

## Copy to: -

- 1. The Commissioner, MCD, Civic Centre, New Delhi- to ensure the occupancy as detailed above.
- 2. M/s "Suzi International" Guest House located at 8483, Arya Nagar, Pahar Ganj, Delhi-110055.
- 3. MHA Portal, ID No. 2024122318315.

## Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MHA portal (https://www.delehlhlic.gov.in) along with a copy of this Certificate, six months prior to its expiry.
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. This FSC is only for total 19 guest rooms from Ground floor to 3<sup>rd</sup> floor only.

1. Name & address of the building:

INSPECTION REPORT

"Suzi International" Guest House located at 8483, Arya Nagar,

Pahar Ganj, Delhi- 110055. 2. Type of occupancy

Residential (A-1) (Total 19 Guest Rooms) 3. Building Comprised of

: Ground Floor (01 Guest Room + Reception + 01 Office), 1st to 3rd floor (06 Guest Rooms at each floor) & 4th Floor (Closed) given an affidavit dated 02/01/2025 regarding not to use any floor above third floor.

Renewal for Ground, 1<sup>st</sup>, 2<sup>nd</sup> and 3<sup>rd</sup> floor.

F6/DFS/MS/GH/NDZ/2021/547 Dated 29/12/2021

4. Type of Case

5. Details of Previous NOC

6. Fire Safety directives letter No Nil 7. Date of inspection 30/12/2024

8. Name of Inspecting Officer R.K.Sinha, ADO (BW)

9. Name and designation of officers

10. From the building side Sh. Naveen Pathak

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement Existing fire safety arrangements	Provided at site	Remarks MR/NMR			
۱.	Access to building						
-	Road width	NA NA	4 m	NA			
2	Gate width	NA	NA	NA			
	Width of internal road	NA	NA	NA			
<b>).</b> ,	Number, Width, Type & Arrangement of Exits						
	Number of staircases						
	Upper Floors	01	01	MR			
	Basements	NA NA	NA	NA			
	Width of staircases	1171		_			
	A WARE MANAGE TO COMPANY OF THE PARK OF TH	0.80 m	1.20 m	MR			
	Upper Floor	NA NA	NA	NA			
	Basements	14/1	3.05.70				
	Protection of exits	NA	NA	NA			
	Fire check door	NA NA	NA	NA			
	Pressurization	NA	1111				
	No. of continuous staircases to terrace	01	01	MR			
	Width of Corridor	NA	NA	NA			
	Door Size	1 m	Provided	MR			
0	577-0700201 (EATH-						
Ų	Compartmentation						
-	Fire check door	NA	NA	NA			
	Sealing of electrical shafts	. NA	NA	NA			
	Fire Rating of shaft door	NA	NA	NA			
	Water Curtain	NA NA	NA	NA			
	Fire Dampers	NA -	NA	NA			
	Smoke Management System						
	Basements	NA	NA	NA			
	Upper floors	Required	Provided	MR			
	Fire Extinguishers						
•							
	Total numbers	10 Nos.	Provided	MR			
	Types	ABC/Co2 Type	Provided	MR			
	IS marking	Required	Provided	MR			
	First-Aid Hose Reels						
	Total numbers on each floor	01	Provided	MR			
	Length of hose reel hose	30 m	Provided	MR			
	Nozzle diameter	5 mm	Provided	MR			

	NAY		4		
	Type of detectors	CO	Provided		MI
	Location of Main Panel	Ground Floor	Provided		MI
	Location of Repeater Panel	NA	NA	nuir	NA NA
	Alternate source of power	Required	Provided	-3	MR
		2011 1200	Strategic locations		MR
0	Hooters' Location	Required	transmitted Assessment		
8.	MOEFA	NA	NA	NA	
9. 10.	Public Address System	Required Provided			MR
10.	Automatic Sprinkler System				
	Basement	- NA			NIA
	Upper Floor	NA NA	NA NA		NA NA
			NA		
11.	Sprinkler above false ceiling	NA	NA		NA
***	Internal Hydrants Size of riser/down-comer				
	Number of hydrod	NA	NA		NA
	Number of hydrants per floor Hose Box	NA	NA NA		NA
12.	Yard Hydrants	NA	NA	- 1	NA
	Total number of hydrants				
	Hose Box	NA	NA		NA
13.	Pumping Arrangements	NA	NA		NA
	Ground Level			- 1	
	Discharge of main Pump	NA	374		6
	Head of Main pump	NA NA	NA NA	-	NA
	Number of main pumps		Managara 2		NA
	Jockey Pump out put	NA	NA	Fr.	NA
	Jockey pump out put  Jockey pump head	NA .	NA		NA
	Standby Pump out put	NA	NA		NA
	Standby Pump Head	NA	NA		NA NA
	Auto Starting/Manual Stopping	NA NA	NA		- NA
		NA	NA		- NA
	Pump House Access	NA	NA		NA
	Terrace level				is the
	Discharge of pump	225 lpm	Provided	V	MR
	Head of the pump	30 m	Provided		MR
	Power Supply	Required	Provided	-	MR
14.	Auto Starting of pump	Required	Provided		MR
14.	Captive Water Storage for fire fight	ing			1
	Underground tank capacity	'NA	NA		
	Draw-off connection	NA .	NA NA	+-	NA NA
	Fire service inlet	NA NA	NA	-	NA NA
	Access to tank	Required	Provided /	+-	NA MR
	Overhead Tank capacity	25,00 ltrs	Provided	-	MR
15.	Exit Signage.	Required	Provided	· ·	MR
6.	Provision of Lifts.	4			
	Decomposition of LiA CL-A	N/A I			
	Pressurization of Lift Shaft	NA NA	NA NA	ll.	NA
	Pressurization of Lift lobby	NA NA	NA		NA
	Communication In lift Car	NA NA	· NA		NA
1	Fireman's Grounding Switch	NA .	NA		ŅA
l	Lift Signage	NA	NA		NA
7.	Standby power supply	Required	Provided		MR
3.	Refuge Area.				
		NA	NIA I	-	N. A.
Ļ	Total Area	NA NA	NA NA		NA NA
-+	Location Fire Centrel Poom	TVA	INA		YA.
).	Fire Control Room				
		NA	NA		NA
7	Detector System Panel	NA NA	NA NA		NA

NIA		
NA	NA	NA
NA	· NA	NA
NA	NA	NA
NA	NA	NA
	NA NA	NA NA NA

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to renew the fire safety certificate issued vide letter no. F6/DFS/MS/GH/NDZ/2021/547 dated 29/12/2021 under rule 37 of the Delhi Fire Service Rules, 2010 if agreed. Accordingly DFA is placed on file, please.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.

CFO Solter is perfy for son when