

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001**

No. F.6/DFS/MS/Hotel/2025/SZ/\6

Dated:03/06 /2025

## FIRE SAFETY CERTIFICATE

Certified that M/s Svelte Hotel & Personal Suites at A-3, District Centre, Select City Walk, Saket, New Delhi -110017 comprised of 03 tiers Basement, Ground floor + 07 Upper floors but the Hotel is from 3rd Floor to 7th floor owned/occupied by Unit of Advent Hospitality Pvt Ltd. was issued FSC by this department vide letter No. F6/DFS/MS/Hotel/2022/SZ/55 dated 26/07/2022. The premise was re-inspected by the officer concerned of this department on 22/05/2025 in the presence of Ms. Manisha Bajpai (GM) of the hotel and observed that fire safety norms as required under Rule 33 of Delhi Fire Service Rules, 2010 are complied and that the premises is fit for occupancy class "Residential, Group-A" (Hotel Building) with effect from 03 /06/2025 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on. 03/04./2025 at New Delhi by.

CHIEF FIRE OFFICER **DELHI FIRE SERVICE** och

Copy to:-

- 1. The Joint Commissioner of Police (Lic.), First Floor, Police Station, Defence Colony, New
- 2. Mr. Devender Mittal, M/s Svelte Hotel & Personal Suites, at A-3, District Centre, Select City Walk, Saket, New Delhi -110017.

## Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

4. The basement shall be used as per the provisions of BBL /NBC Part- IV.

5. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization of

unauthorized construction, if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

## **INSPECTION REPORT**

e & address of the building: M/s Svelte Hotel & Personal Suits, select City Walk, A-3 District

Center, Saket, New Delhi-110017

of Occupancy : Group A "Hotel Building"

type of Case : Renewal

Comprised of : 3B+G+7 upper floors but Hotel is running at  $3^{\text{rd}}$  floor to  $7^{\text{th}}$  floor only Details of Previous NOC

: F6/DFS/MS/Hotel/2022/SZ/55 dated 26/07/2022 Fire Safety directives letter No : Nil

Date of inspection : 22/05/2025

Name of Inspecting Officer : Sh. Rajesh Kumar ADO (BCP)

Name and designation of officers

From the building side : Ms. Manisha Bajpai (GM)

10. Year of Construction : 2007

11. Applicant's letter No. : Outdoor diary no 1348 dated 05/05/2025

	Minimum Standards on fire prevention	NBC/BBL	Provided at site	Remarks			
0.	and fire safety U/R 33	Requirement		MR/NMR			
1	Access to building Select City Mall FSC No. of F6/DFS/MS/Mall/2022/SZ/335 dated 27/07/2022						
	<ul> <li>Road width</li> </ul>	09 mtr	Provided	MR			
	<ul> <li>Gate width</li> </ul>	05 mtr	Provided	MR			
	<ul> <li>Width of internal road</li> </ul>	06 mtr	Provided	MR			
2.	Number, Width, Type & Arrangement of Exits [Provided & Maintained by Mall management]						
	a. Number of staircases						
	Upper Floors	02 Nos for hotel	Provided*	MR			
	Basements	16 Nos	Provided*	MR			
	b. Width of staircases						
	Upper Floor	1.50 mtr each	Provided*	MR			
	Basement	2 mtr, 1.50 mtr &	Provided*	MR			
	c. Protection of exits		D 11	) M			
	Fire check door	Required	Provided	MR			
	<ul> <li>Pressurization</li> </ul>	Required	Provided	MR			
	d. No. of continuous staircases to terrace	Required	2 No's	MR			
	e. Width of Corridor	Required	1.5m	MR			
1	f. Door Size	1m	1m	MR			
3.	Compartmentation						
	Fire check door	Required	Provided	MR			
	<ul> <li>Sealing of electrical shafts</li> </ul>	Required	Provided	MR			
	Fire Rating of shaft door	Required	Provided	MR			
	Water Curtain	NA	NA	NA			
	Fire Dampers	Required	Provided	MR			
_		[Provided & Maintained by Mall management]					
4.	Smore Wanagement System						
	Basements	12 ACPH	Provided	MR MR			
	Upper floors	12 ACTII	Tiovided	IVAC			
5.	5. Fire Extinguishers 40 No's Total-50 No's						
	Total numbers	ISI marked	ABC-30 No's	MR MR			
	• Types	151 Illai keu	CO <sub>2</sub> /W.CO <sub>2</sub> -20 No's				
	IS marking		CO2/W.CO2-20 NO S	IVIIC			
6.		T M-2-	Provided	MR			
	Total numbers on each floor	Two No's 30 m	Provided	MR			
	<ul> <li>Length of hose reel hose</li> </ul>	50 m	Provided	MR			
	Nozzle diameter						
'	7. Automatic fire detection and alarming	System	Smoke & Heat	MR			
	Type of detectors	Required Required	Sec. Control Room				
	Location of Main Panel	Required	AND THE PROPERTY OF THE PARTY O	MR			
	<ul> <li>Location of Repeater Panel</li> </ul>	Required	Provided	IVIN			

		•				
	<ul> <li>Alternate source of power</li> </ul>	Required	Provided	MR		
-	<ul> <li>Hooters' Location</li> </ul>	Required	All Floors	MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
10.	. Automatic Sprinkler System					
	<ul> <li>Basement</li> </ul>	Required	As Above	NA		
	<ul> <li>Ground Floor</li> </ul>	Required	Provided	MR		
	Sprinkler above false ceiling	Required	Provided	MR		
11.	Internal Hydrants					
	<ul> <li>Size of riser/down-comer</li> </ul>	150mm	150mm	MR		
	<ul> <li>Number of hydrants per floor</li> </ul>	Two	Provided	MR		
	Hose Box	Two	Provided	MR		
12.	Yard Hydrants	Provide	ed & Maintained by M	(all management)		
	<ul> <li>Total number of hydrants</li> </ul>	Required	Provided	MR		
	Hose Box	Required	Provided	MR		
13.	Pumping Arrangements	[Provided	& Maintained by M	all management]		
	Ground Level					
	Discharge of main Pump	4500 LPM	Provided	MR		
	► Head of Main pump	88m	Provided	MR		
	Number of main pumps	02No	Provided	MR		
	Jockey Pump out put	180 LPM	Provided	MR		
	Jockey pump head	88m	Provided	MR		
	Standby Pump out put	4500 LPM	Provided	MR		
	<ul><li>Standby Pump Head</li><li>Auto Starting/Manual Stopping</li></ul>	88m	Provided	MR		
	> Pump House Access	Required	Provided	MR		
	Terrace level	Required	Provided	MR		
	Discharge of pump					
	➤ Head of the pump	NA	180 LPM	NA		
	➤ Power Supply	NA	88m	NA		
	Auto Starting of pump	NA NA	Provided	NA		
4.	Captive Water Storage for firefighting	NA (Provided & M	Provided	NA		
		aintained by Mall ma				
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>	5,00,000 ltrs	5,00,000 ltrs	MR		
	Fire service inlet	Required	Provided	MR		
	> Access to tank	Required	Provided	MR		
	Overhead Tank capacity	Required	Provided	MR		
5.	Exit Signage.	30,000 ltrs	30,000 ltrs	MR		
_	Provision of Lifts.	Required	Provided	MR		
· .						
	Pressurization of Lift Shaft	Required	Provided	MR		
	Pressurization of Lift lobby	Required	Provided	MR		
	• Communication In lift Car	Required	Provided	MR		
	• Fireman's Grounding Switch	Required	Provided	MR		
.	Lift Signage  Standby power supply	Required	Provided	MR		
-	Refuge Area.	Required	Provided	MR		
+	> Total Area	Paguine 1				
	> Location	Required Required	543 Sq. feet	MR		
1	Fire Control Room	required	4 <sup>th</sup> & 6 <sup>th</sup> Floor	MR		
+	Detector System Panel	Required				
	Flow Switch Panel	Required	Provided	MR		
	PA System Panel	Required	Provided	MR		
	Batter backup	Required	Provided	MR		
1	-	1	Provided	MR		
	Building Floor Plans					
	Building Floor Plans	Required	Provided	···IX		

2/29

Fire Protection System for Protection of special Risks, if any:

NA

\* Fire Safety arrangements provided & maintained by Mall management of A-3 District Centre select City Walk, Saket, New Delhi.

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire measures as required under the rules, the FSC issued vide F6/DFS/MS/Hotel/2022/SZ/55 dated 26/07/2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly FSC in shape of DFA is put up for approval.

Signature of Inspecting Officer Name: - Sh. Rajesh Kumar Designation: - ADO (BCP)

or your synatur !

po scell