

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/GH/SZ/2025/ 345

Dated: 15

## FIRE SAFETY CERTIFICATE

Certified that the M/s The Beaufort Inn Guest House located at 14/746, Main Mathura Road, Jung Pura, New Delhi-110014, was granted Fire Safety Certificate (FSC) by this department vide letter no. F6/DFS/MS/GH/SZ/2022/55 dated 25.01.2022 for Basement + Ground + 02 upper floors. The Guest House was re-inspected by officer concerned of this department on 10.05.2025 in presence of Sh. Anil (Manager) and found that Guest House building is now comprised of Basement + Ground + 03 upper floors: Basement - Storage, Ground floor - Reception + 05 guest rooms, 1st floor - 06 Guest rooms, 2nd floor- 06 Guest rooms, 3rd floor-01 room + Kitchen + terrace. The Guest House has complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of Group 'A (Residential), sub division A-1, total 18 guest rooms (Ground floor - Reception + 05 guest rooms, 1st floor - 06 Guest rooms, 2nd floor- 06 Guest rooms, 3rd floor - 1 Guest Room + kitchen) with effect from .15 0.5 2025 and valid upto 31.03.2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 Issued on 15 05 2025 at New Delhi by printed below.

Delhi Fire Service

Reference: elt.mcdonline application no. 2025050107624.

Copy to-

1. The Commissioner, MCD, Dr. S.P.M. Civic Centre, Minto Road, New Delhi-110002:- To ensure the occupancy as detailed above.

## Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The means of escape shall be kept unobstructed/unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

1	Non		CTION REPOR			
		e & address of the building	M/s The Beaufort Inn Guest House located 14/746, Main Mathura Road, Jung Pura, No. Delhi-110014.			
2	Building is comprised of		Basement + Ground + 03 upper floors Basement - Storage			
			Ground - Reception + 04 guest rooms			
			1 <sup>st</sup> floor - 06 guest rooms 2 <sup>nd</sup> floor - 06 guest rooms			
			3rdfloor - 01roon	m + Kitchen		
3	Type of occupancy Residential Sub Division- A-1					
4	Type of case  Renewal/addition of kitchen and 01 guest room  3 <sup>rd</sup> floor of the existing building after regular from MCD.					
5	Deta	ils of previous FSC	F6/DFS/MS/GH/SZ/2022/55 dated 25.01.2022 for Basement + Ground + 02 upper floors			
6	Fire	safety directive letter no.	Nil			
7		of inspection	10.05.2025			
8				Shulds ADO AA D	oad)	
100		e of the inspecting officers		Shukla, ADO (M. R	.oad)	
9	Fron	ne of the designation of officer in the building side	Manager			
10		r of construction	2000			
11	App	licant's letter no.	elt.mcdonline application no. 2025050107624			
S. No	100 cm 440-	nimum standard of Fire vention and Fire Safety U/R	Requirement as per Rule 35 (6)	Provide at site	Remarks MR/NMR	
1		ess to Building	Lizza	T • • •	1.00	
	A	Road width	6.0 m	Provided	MR	
	В	Gate width	NA	NA	NA NA	
	C	Width of internal roads	NA SErita	NA	NA	
2		nber, Width, Type & Arrange	ement of Exits	-		
	A	No. of staircase:	11	Provided	MR	
		a) Upper floor	1 no. 2 nos.	Provided	MR	
		b) Basements	Z nos.	Provided	MIK	
	В	Width of the staircase:	1.25	1.25 m	MD	
		a) Upper floors	1.25 m 1.25 m	1.70 m & 1.10 m	MR MR	
	-	b) Basements	1.23 m	1.70 m & 1.10 m	IVIK	
	C	Protection of exits	NA	NA	NA	
		a) Fire check door b) Pressurization	NA NA	NA	NA NA	
	D	No. of continuous staircase to terrace:	1 no.	Provided	MR	
	E	Width of the corridor	NA	NA	NA	
	F	Door size	1.0 m	Provided	MR	
3	Cor	npartmentation:	<u> </u>			
	A	Fire check doors	NA	NA	NA	
	В	Sealing of horizontal & vertical opening	NA	NA	NA	
				NA	NA	
	C	Fire rating of shaft doors	NA		the state of the s	
	D	Water curtain	NA	NA	NA	
	D E	Water curtain Fire dampers	A STATE OF THE PARTY OF THE PAR		the state of the s	
4	D E Sn	Water curtain Fire dampers toke Management System:	NA NA	NA NA	NA NA	
4	D E Sn A	Water curtain Fire dampers toke Management System: Basements	NA NA Required	NA NA Exhaust fans	NA NA MR	
	D E Sn A B	Water curtain Fire dampers  toke Management System: Basements Upper floors	NA NA	NA NA	NA NA	
5	D E Sn A B	Water curtain Fire dampers  toke Management System: Basements Upper floors  e Extinguishers	NA NA Required Required	NA NA Exhaust fans Exhaust fans	NA NA MR MR	
	D E Sn A B	Water curtain Fire dampers  toke Management System: Basements Upper floors	NA NA Required	NA NA Exhaust fans	NA NA MR	

N)36

5	Fir	st Aid Hose Reel		l no.	MR		
	A	Total no. at each floor	1 no.	30 m	MR		
	В	Length of hose reel	30 m	5 mm	MR		
	C	Nozzle diameter			per clau		
7	C Nozzle diameter 5 mm  Automatic Fire Detection and Alarm System (ADAS) (Required as per claus						
	7.31	L.viii, UBBL 2016).		Provided	MR		
	A	Type of detectors	CO detector	Provided	MR		
	В	Location of main Panel	At ground	NA	NA		
	C	Location of repeater panel	NA		NA		
	D	Alternate power source	NA	NA Provided	MR		
	E	Hooter's location	Audible in		IVII		
	-		entire building	Dunnidad	MR		
8	-	DEFA	Required	Provided	MR		
9		olic Address System	Required	Provided	MK		
10		tomatic Sprinkler System			1.00		
	A	Basement	Required	Provided	MR		
	В	Upper floor	NA	NA	NA		
	C	Sprinklers above false ceiling	NA	NA	NA		
11	Inte	ernal hydrants					
	A	Size of the riser/down comer	NA	NA	NA		
	В	No. of hydrants per floor	NA	NA	NA		
	C	Hose box	NA	NA	NA		
12	_	rd Hydrants					
	A	Total no. of hydrants	NA	NA	NA		
	В	Hose box	NA	NA	NA		
13	Pumping arrangements						
	A	Ground Level					
		a) Discharge & head of main pump	NA	NA	NA		
		b) Number of main pump	NA	NA	NA		
		c) Discharge & head of jockey	NA	NA	NA		
		pump					
		d) Discharge & head of Standby	NA	NA	NA		
		pump					
		e) Auto starting/ manual stopping	NA	NA	NA		
	В	Terrace Level	450 7 77 5				
		a) Discharge of terrace pump	450 LPM	450 + 180	MR		
		b) Head of terrace pump	40 m	LPM			
		c) Alternate power supply	Required	40 m	MR		
		d) Auto starting of pump	Required	Provided	MR		
14	Car	otive Water Storage for Fire Fighting		Provided	MR		
	A	Underground tank capacity	NA	NA	T		
	B	Draw off connection	NA NA	NA NA	NA		
	C	Fire Service Inlet	NA NA	NA NA	NA		
	E	Access to tank	NA	NA NA	NA		
	D	Overhead tank capacity	5,000 ltrs	Provided	NA		
15	Exi	t Signage	Required	Provided	MR		
16	Pro	vision of lift		Tovided	MR		
	A	Pressurization of lift shaft	NA	NA	NA		
	В	Pressurization of lift lobby	NA	NA	NA NA		
	C	Communication in lift car	Required	Provided	MR		
	D	Fireman switch		Provided	MR		
	E	Lift signage	Required	Provided	MR		
17		ndby Power Supply	Required	Provided			

M/s The Beaufort Inn Guest House located at 14/746, Main Mathura Road, Jung Pura, New Delhi-110014.

18	Refuge Area					
	A	location	NA	NA	NA	
	В	Total area	NA	NA	NA	
19	Fire Control Room					
	A	Fire Detection System panel	NA	NA	NA	
	В	Flow switch panel	NA	NA	NA	
	C	P A system panel	NA	NA	NA	
	D	Battery backup	NA	NA	NA	
	E	Building floor plan	NA	NA	NA	
20	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
	A Special Fire Protection system for Protection of Special Risk, if any:				NA	

LEGENDS:-Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

Note: The Guest House Management has converted an existing pantry at ground floor into a Guest Room and added 01 Guest room + 01 kitchen at terrace and has submitted a copy of the regularized plan which is placed on C/111 on the file. The same has been regularized by the local building sanctioning authority as per the existing norms of the building without any further change in the requirements. This department may accept the regularized plan.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

If agreed to the note above and in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/SZ/2022/55 dated 25.01.2022 is recommended to be renewed for total Eighteen Guest (18) Rooms with Kitchen, under Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

muu muu

115/5/2025

Directary 1818/

V Mandel 16/8/88

B