GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

o.:F6/DFS/MS/GH/NDZ/2025/ 143

Dated: 19/03/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s The Bella Express at Plot No. 56, Arakashan Road, Pahar Ganj, New Delhi- 110055, comprised of Stilt + Ground + 03 upper floors: Stilt - (parking), ground floor- (07 guest rooms), 1st floor - (07 guest rooms), 2nd floor- (07 guest rooms) & 3rd floor - (04 guest rooms), total 25 guest rooms. The building/ premises was inspected by the team of officers concerned of this department on dated 07.03.2025 in presence of Mr. Mohit Chawla (Owner) and found that the building have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of "Residential (Sub Division-A-1), Stilt + Ground + 03 upper floors: Stilt - (parking), ground floor- (07 guest rooms), 1st floor - (07 guest rooms), 2nd floor- (07 guest rooms) & 3rd floor- (04 guest rooms) for total 25 guest rooms, with effect from ... 19 23 20 25. for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on 19103 2025 at New Delhi by

Director Director Thi Fire Service

Tel: 011-23414000

Copy to:-

1. The Commissioner, MCD:- to kindly ensure the occupancy as detailed above, if any.

 The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi. w.r.to ID No. 2025022402363 dated 25.02.2025.

3. The Licensee, M/s The Bella Express at Plot No. 56, Arakashan Road, Pahar Ganj, New Delhi-110055.

Conditions for the validity of Fire Safety Certificate

- 1. This FSC for guest rooms is valid for ground to 3rd floor only in the building.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

			INSPE	CTION REPORT			
	Name & address of the building			M/s The Bella Arakashan Roa 110055.	M/s The Bella Express at Plot No. 56, Arakashan Road, Pahar Ganj, New Delhi- 110055.		
	Building is comprised of Type of occupancy Type of case Details of previous FSC Fire safety direction letter no. Date of inspection			28 as 9 7 36 as	(Stilt + Ground + 03 upper floors) Stilt - (parking) Ground floor - (07 guest rooms) 1 st floor - (07 guest rooms)		
				2 nd floor – (07 guest rooms) 3 rd floor – (04 guest rooms)			
					Residential (Sub-Division-A-1)		
1				New Case			
4							
5				NA UBBL/ NBC Part - IV-2016			
6							
7					07.03.2024		
8	Name of the inspecting officers			DO (CD) & ADO	A STATE OF THE STA		
9	Nar	ne	of the designation of	f Mr. Mohit Chaw	Mr. Mohit Chawla (Owner)		
	offi	cer	from the building side				
10	Yea	ar of	construction	2024	I I		
11	Applicant's letter no.			Online applicati	Online application no. 2025022402363 dated		
		12		25.02.2025	25.02.2025		
S.No	Mi	nim	um Standards on fire	Requirements	Provided at Site	Remarks	
	Pre	ever	tion and fire safety	as per		MR/	
	req	luir	ements U/R 33	UBBL/NBC		NMR	
				Part IV -2016	Part IV -2016		
1	Access To Building:				D	MR	
			vidth	06 mtrs.	Provided		
	Gate width			NA	NA	NA	
	1000		of internal road	NA	NA	NA	
2	+		er, Width, Type and Arra	angement of Exits:			
	A	-	umber of staircases	02	02 nos.	MR	
		b	Upper floor	02 nos. NA	NA	NA	
	n		Basement	INA	INA	INA	
1	В	-	idth of staircases	1.50 m each	1.50 m each /	MD	
		-	Upper floor Basement	NA	NA NA	MIR NA	
	C		otection of exits	IVA	INA	INA	
	Ĕ	_	Fire check door	NA	NA	NA	
		_	Pressurization	NA NA	NA NA	NA NA	
	D	_	o. of continuous staircases		02 nos.	MR	
		- 25	terrace			WIII	
	E	+	idth of corridor	1.80 m & 1.50	Provided /	MR	
	L	1		m			
						The second second	
	F	_	oor size	1.0 mtr.	1.0 mtr.	MR	
3	F	mp	artmentation:	1.0 mtr.	1.0 mtr.	MR	
3	F Co	mp:	artmentation: ire check door	1.0 mtr.	1.0 mtr.		
3	F Co A B	mp:	artmentation: ire check door ealing of electrical shafts			NA	
3	F Co A B	F S F	artmentation: ire check door ealing of electrical shafts ire rating of shaft door	NA	NA	NA NA	
3	F Co A B C	F S F	ire check door ealing of electrical shafts ire rating of shaft door Vater curtain	NA NA	NA NA NA	NA NA NA	
	F Co A B C D	F S F V	ire check door ealing of electrical shafts ire rating of shaft door Vater curtain ire dampers	NA NA NA	NA NA NA	NA NA NA NA	
3	F Co A B C D E	F S F V F	artmentation: ire check door ealing of electrical shafts ire rating of shaft door Vater curtain ire dampers e Management System:	NA NA NA NA	NA NA NA	NA NA NA	
	F Co A B C D	F V F	ire check door ealing of electrical shafts ire rating of shaft door Vater curtain ire dampers	NA NA NA NA	NA NA NA	NA NA NA NA	

A B	Total numbers	10 nos.	10 nos.	
В		CO ₂ & ABC	CO ₂ & ABC	MR
	Types	A. A. C.		MR
C	ISI marking	Required	Flovides	
First-Aid	l-Hose Reels:	III-	Provided	MR
A	Total numbers of each	01 no.	Flovided	0.2020
4/	floor	30 m	30 m	MR
(B)		5201 SA	05 mm	MR
C		10.5		
Automat	ic Fire Detection And Alarn	ning System:	Provided	MR
A		Required	110,124	-
	type)	Required	Provided	MR
B	Location of main paner	NA	NA	NA
C			A residence of	MR
D	Alternate source of power	Required		MR
	Hooters	Required		MR
	(1.55 pt 4.55		1 ISSANS	NA
(基本語しませき)		NA	NA	MA
Automat	ic Sprinkler System:		1	NA
	Basement	NA	1827.887.1	NATIONAL CONTRACTOR
	The second disease	NA	Provided	NA
1,000		NA	NA	NA
C				
Internal				NIA
	size of riser/down-comer	NA		NA
United and		NA	01	NA
R				NA
C		NA	01	INA
				1314
	Total number of hydrants	NA .	NA	NA
		NA	NA	NA
1.00				
Pumping	Arrangements:			
A	Ground level	NΔ	NA	NA
a)			(*) · .	NA
b)				NA
	Number of main pumps			NA
	Jockey pump out put			
		NA		NA NA
		NA	2765-527	10.000000000000000000000000000000000000
		NA		NA
	Auto starting /manual	NA	NA	NA
,			****	NA
i)	Pump house access	NA	NA	INA
	Terrace level	je de la companya de		1 200
a)	Discharge of pump	450 LPM	450 LPM - 02 nos.	
Ы	Head of the pump	40 mtrs.	40 mtrs.	MR
		Required	Provided	MR
d)	Auto starting of pump	Required	Provided	MR
	B C Automat A B C D E MOEFA Public A Automat A B C Internal A B C Yard Hy A B Pumping A a) b) c) d) e) f) g) h) i) B a)	floor B	Required Required	Total numbers of each floor So min So min

_		otive Water Storage For Fire F	NA	NA	NA
-	A	Underground tank capacity	NA NA	NA -	NA
5	В	Draw-off connection		NA	NA
10	C	Fire service inlet	NA	Provided	MR
8	D	Access to tank	Required	15,000 ltrs.	MR
- [E	Overhead tank capacity	5,000 ltrs.	Provided	MR
15	Exi	it Signage:	Required		\
16	Provision of Lifts:		Provided		NA
+	A	Pressurization of lift shaft	NA	NA	NA NA
-	B	Pressurization of lift lobby	NA	NA	MR
1	C	Communication in lift car	Required	Provided	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
-		Firemen's grounding switch	Required	Provided	MR
	D	1000	Required	Provided	MR
	E	Lift signage	Required	Provided	MR
17	Sta	andby Power Supply:	Required	- WAR	
18	Re	fuge Area:	NA	NA	
	A	Total area	NA	NA NA	NA
	В	Location	NA	INA	
19	Fi	NIA	NA		
	A	Detector system panel	NA	NA NA	NA
	B	Flow switch panel	NA	NA NA	NA
	C	Pa system panel	NA	NA NA	NA
	D	Battery backup	NA	NA NA	NA
	-	n '11' floor plane	NA	NA NA	NA
20	Sı	pecial Fire Protection Systems Forcial Risks, If Any:	were tested, che		

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

In view of the substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate for under Rules 35 of the Delhi Fire Service Rules 2010.

Accordingly, DFA is put for approval and signature please.

the Inspecting Officer Signature of

Name

Rajinder Atwal

Designation

DO (CD)

Signature of the Inspecting Office

Name

Sumit Kumar

Designation

ADO (SPM)