

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001

प्रास्त । एक करा स्ताप्रदा की और

No. F.6/DFS/MS/Hotel/2025/SZ/ 2 7

Dated: 03/09/2025

FIRE SAFETY CERTIFICATE

Certified that M/s The Claridges Hotel located at 12, Dr. APJ Abdul Kalam Road, New Delhi–110011, comprised of Basement, Ground + 03 upper floors, owned/occupied by A Unit of Claridges Hotel Pvt. Ltd, was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/Hotel/2023/SZ/04 dated 30/01/2023. The premise was re-inspected by the officer concerned of this department on 08/08/2025 in the presence of Sh. Jaswinder Singh (Director-Compliance Coordinator) and found that the said building/premises (Basement, Ground + 03 upper floors) is fit for occupancy class "Residential Group A-6" (Starred Hotel) with effect from \(\frac{1}{2} \) \(

Issued on 68 / 69 /2025 at New Delhi by

(Virendra Singh)
Chief Fire Officer
Delhi Fire Service

Copy to: -

- 1. The Commissioner, MCD, Civic Centre, JLN Marg, Minto Road, New Delhi-110002
- 2. Sh. Jaswinder Singh (Director-Compliance Coordinator), M/s The Claridges Hotel located at 12, Dr. APJ Abdul Kalam Road, New Delhi-110011

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. Basement shall be used strictly in accordance with the BBL.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this certificate, prior to its expiry.

	RINSPECT	ION REPORT					
1.	Name & address of the building	The Claridges Hotel (A Unit of Claridges Hotel Pvt. Ltd) at 12, Dr. APJ Abdul Kalam					
		Road, New D	eihi-110011	ıı Kalam			
2.	Type of Occupancy	Residential "(Group A-6"				
3.	Building Comprised of	Basement + Ground + 03 upper floors.					
4.	Type of Case	Renewal					
5.	Details of previous NOC No.	F6/DFS/MS/Hotel/2023/SZ/04 dated 30/01/2023					
	Fire Safety directives letter No.	F6/DFS/MS/79-18 dated 19/01/1978					
6.		F6/MS/DFS/79-210 dated 17/06/1979					
7.	Date of inspection	08/08/2025	08/08/2025				
8.	Name of the Inspecting Officer	ADO (SJ)					
9.	Name and designation of Officer	Sh. Jaswinder Singh (Director-Compliance					
7.	from the building side	Coordinator)					
10.	Year of Construction	1952					
11.	Applicant's letter No.	No. Nil dated 11/07/2025 received through Outdoor Diary No. 3823 dated 16/07/2025					
S.	Minimum standards on fire	Old NOC	Provided at site	Remark			
No.	prevention and fire safety U/R 33	Requirement		MR/NM			
1.	Access of building	06	24	MR			
	Road width	06 mtr	24 mtr	MR			
	Gate width	05 mtr	Provided	17,000			
	 Width of internal road 	N/A	N/A	N/A			
2.	Number, width, Type & Arrangements of exits						
	a. Number of staircases	7					
	Upper floors	GF to 2 nd F=5nos GF to 2 nd F=5nos 2 nd F to 3 rd F=3nos 2 nd F to 3 rd F=3nos		MR			
		2 nd F to 3 rd F=3nd 03 Nos	02 Nos + 1 Ramp	(old case			
	Basements	05 1908	02 1103 · 1 144111p				
	b. Width of staircases	1.50 mtr	1.20 mtr each	MR			
	Upper floorsBasements	1.50 mtr	1.20 mtr & 04 ramp	(Old Case			
	c. Protection of exits	53/46/18		20 2000			
	Fire check door	Required	Provided	MR			
	Pressurization	N/A	N/A	N/A			
	d. No of continuous staircase to terrace	Required	03 Nos	MR			
	e. Width of Corridor	N/A	N/A	N/A MR			
	f. Door Size (Final Exit)	1 mtr	1 mtr (Final exit)	IVIK			
3.	Compartmentation	27/4	N/A	N/A			
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A N/A	N/A	N/A			
	Fire Rating of shaft door	N/A N/A	N/A	N/A			
	Water Curtain	N/A N/A	N/A	N/A			
Λ	Fire Dampers Smales Managements System	INIA	Service of the servic				
4.	Smoke Managements System	30 ACPH	Exhaust fan provided	MR			
	Basements	12 ACPH	Exhaust fan provided	MR			
-	• Upper floors	12710111	<u> </u>				
5.	Fire Extinguishers	25 Nos	46 Nos	MR			
	Total numbers	ABC/CO ₂	ABC & W.CO ₂	MR			
	• Types	ISI marked	Provided	MR			
- N-E	ISI marking	131 IIIalkeu					
6.	First-Aid Hose Reels	BF-02, GF-08, FF &	BF-02, GF-08, FF &	MR			
	Total numbers on each floor	SF-06, 3 rd F-03nos	SF-06, 3 rd F-03nos				
	Length of hose reel hose	30m	30m	MR MR			
	Nozzle diameter	5mm	5mm	IVII			

N-54

	 Type of detector Location of Main Panel 	Heat & Smoke	Provided Provided	MR
	Lantion of Main Danal		PIOVIGCO	
1		Required	N/A	N/A
1	Location of Repeater Panel	N/A Provinced	Provided	MR
	Alternate source of power	Required	Provided	MR
	Hooters' Location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	
10.	Automatic Sprinkler System	T	Provided	MR
	Basements	Required	THE STREET STREET STREET	MR
	Upper Floor	Required	Provided	MR
	 Sprinkler above false ceiling 	Required	Provided	IVIIC
11.	Internal Hydrants			MD
	Size of riser/down- comer	150 mm	Provided	MR
	 Number of hydrants per floor 	02 Nos	03 Nos	MR
	Hose Box	02 Nos	03 Nos	MR
12.	Yard Hydrants			
	Total number of hydrants	04 Nos	Provided	MR
	Hose Box	04 Nos	Provided	MR
13.	Pumping Arrangements	CO TAC THEODOL		
	Ground Level			
	Discharge of main pump	2250 LPM	2500 LPM	MR
	Head of main pump	60 mtr	60 mtr	MR
	Number of main pumps	2 Nos	2 Nos	MR
	Jockey pump out put	180 LPM	220 LPM	MR
	> Jockey pump head	60 mtr	60 mtr	MR
	Standby Pump out putStandby Pump Head	2250 LPM	2500 LPM	MR
	Auto Staring/Manual stopping	60 mtr	60 mtr	MR
	Pump House Access	Required	Provided	MR
-	Terrace level	Required	Provided	MR
	Discharge of pump	N/A	27/4	
	> Head of the pump	N/A	N/A	N/A
	➤ Power supply		N/A	N/A
	> Auto starting of pump	N/A	N/A	N/A
14.	Captive water Storage for fire fighting	N/A	N/A	N/A
	Underground tank capacity		42	
	Draw of connection	1,50,000 Lts	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	7-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0	Required	Provided	MR
15	Overhead Tank capacity Exit Signage	20,000 ltrs	70,000 ltrs	MR
16.	Provision of Lifts	Required	Provided	MR
	- 1005dilZation of Lift Shart	N/A	N/A	N/A
*	Pressurization of lift lobby	N/A	N/A	N/A
	Communication in fill Car	Required	Provided	MR
	Fireman's Grounding Switch	Required	Provided	
15	► Lift Signage	Required	Provided	MR
17.	Standby Power Supply	Required	Provided	MR
18.	Refuge Area	- roquired	Trovided	MR
10.				
10.	Total area	N/A	N/A	N/A



Fire Control Room			1.00
> Detector system panel	Required	Provided	MR
 Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A
	Required	Provided	MR
	Required	Provided	MR
	N/A	N/A	N/A
Special Fire Protection Systems for Protection of Special Risks, if any;	3 (1) (2)		MR

The fire protection systems provided in the premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F.6/DFS/MS/Hotel/2023/SZ/04 dated 30/01/2023, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA letter is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

Minipal Dinector

AD(CSD) Mayor

ADO(CSD) Mayor

ADO(CSD) Mayor

Sir, F.T with in pulling for your sing. p. C. Fold Mayor

CFO/MR Mayor

CFO/M