

2/98

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/ 211

Dated: 02/05/2025

To,

The Manager,
M/s The Grand Shoba,
Kh. No. 1031/1, Street no.6,
Mahipalpur New Delhi-110037.

Sub: Regarding issuance of FSC in r/o M/s The Grand Shoba Kh. No. 1031/1, Street no.6, Mahipalpur New Delhi-110037.

Sir,

This has reference to online id no. 2025041306333 dated 13.04.2025, on the subject cited above. In this connection, it is to inform you that the site was inspected by the officer concerned of this department on 26/04/25 in the presence of Mr. Vikram Singh and observed that this is case of addition/alteration in the existing guest house and addition of guest rooms. During the inspection following shortcomings were observed:-

- 1) Alternate Staircase of 1.5 meter is not provided.
- 2) Fire check door not provided at alternate staircase.
- 3) Width of corridor of 1.80 m is not provided.

In view of above, the case is rejected and Fire Safety Certificate (FSC) cannot be issued at this stage due to above shortcomings. Therefore, you are requested to rectify the above shortcomings and re-submit for further consideration in the matter

Yours faithfully,

(Atul Garg)
DIRECTOR
Delhi Fire Service

Copy to :-

1. The Commissioner, MCD, Civic Centre, New Delhi.
2. The Addl. Commissioner of Police (Lic.) First floor, PS Defense Colony, New Delhi.