

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/2025/643

Dated :08/12/2025

## FIRE SAFETY CERTIFICATE

Issued . 08 12 1025 at New Delhi by.

(Dr. S. K. Tomar) Dy. Chief Fire Officer Delhi Fire Service

0/c Bf

Copy to: -

1. The Chief Architect, NDMC, Palika Kendra, New Delhi

2. The General Secretary, The Indian Newspapers Society located at Rafi Marg, New Delhi.

## Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The trained firefighting staff should be available round the clock.

- 4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
- 9. Any flammable material for interior decoration is prohibited.

## N/24

		CTION REPORT			
1.	Name & address of the building	The Indian Newspapers Society, I.N.S. Building, Rafi Marg, New Delhi.			
2.	Type of occupancy	Business Building Existing Block – Gr. + 05 Upper Floors			
		Extension Block - both block Joint to	B+Stilt/Gr.+06 Uppe	er Floors &	
3.	Type of case	Renewal			
4.	Details of previous FSC No.	No.F6/DFS/MS/NDZ/2022/325 Dated 25/07/2022			
5.	Fire safety directives No	N/A			
6.	Date of inspection: -	27/11/2025			
7.	Name of the inspecting officer: -	Sh. Manish Kumar, DO(CD) Sh. Bhupender Prakash, ADO(CC)			
8.	Name & designation of officer From the building side: -	Sh. Himanshu (Asstt. Admin)			
9.	Year of construction: -	1985-86			
10.	Applicant's letter No: -	Letter dated 13/09/2025  Remarks  Remarks			
S. No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	MR/NMR	
1.	Access to Building			MD'	
	Road width	06 mtr.	09 mtr.	MR'	
	Gate width	4.5 mtr.	4.5 mtr.	MR	
×	Width of internal road	N/A	Approachable from front & rear side	N/A	
2.	Number, Width Type & Arran	gement of Exits			
	a. Number of staircases		102	MR	
	Upper floors	03 nos.	03 nos.	MR	
	Basements	1.25 mtr. & ramp	1.25 mtr. & ramp	IVIIC	
	b. Width of staircase		T = 10 0 1 10 mtr	MR(Old Ca	
	Upper floors	1.25 mtr.	0.60, 1.40 & 1.40 mtr.	MR	
	Basements	1.25 mtr. & ramp	1.25 mtr. & ramp	WIIC	
	c. Protection of exits		N//4	N/A	
	Fire check door	N/A	. N/A	N/A	
	Pressurization	N/A	N/A	N/A	
	d. No. of continuous	N/A	01 nos.	INIA	
	staircase to terrace		NIA	MR	
	e. Width of corridor	N/A	N/A	MR	
	f. Door size	1 mtr.	1 mtr.	IVIIC	
3.	Compartmentation		D 11.1	MR	
J.	<ul> <li>Fire check door</li> </ul>	Required	Provided	MR	
	<ul> <li>Sealing of electrical shafts</li> </ul>	Required	Provided	N/A	
	<ul> <li>Fire rating of shaft door</li> </ul>	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	Fire Dampers	N/A	N/A	IWA	
4.	Smoke Management System		In unin	MR	
	Basements	12 ACPH	Provided Exhaust Fan		
	Upper floors	Required	Provided Natural	MR	
5.	Fire Extinguishers	the state of the s		MD	
	Total numbers	30 nos.	32 nos.	MR	
	Types	ABC & CO <sub>2</sub>	ABC & CO <sub>2</sub>	MR	
	ISI marking	Required	Provided	MR	
6.	First-Aid Hose Reel	Jet a.		2 200	
0.	Total number of each floor	02 nos.	Provided	MR	
	a de la la companya de la companya del companya de la companya del companya de la	30m	Provided	MR	
Ť	102 Y 100 2	5mm	Provided	MR	
	Nozzle diameter  Automatic Fire Detection & Alarn		The second secon		
7.					

The Indian Newspapers Society, I.N.S. Building, Rafi Marg, New Delhi.

osf

	25
M	1

			Provided	N/A
	2 1 2	Required	N/A	MR
	Location of main panel	N/A	Provided	MR
	a Location of repeater panel	Required	Provided	MR
	Alternate source of power	Required	Provided	MR MR
	Hooter's Location	Required	Provided	IVIK
	MOEFA	Required	Provides	11/10
. 1	Public Address System	Avy	Provided	MR
0.	Automatic Sprinkler System	Required	Provided	N/A
	Basement	N/A		N/A
	Upper floors	N/A	N/A	
	Sprinkler above false	6.M.		
	ceiling		1.50	MR
11.	Internal Hydrants	150mm	150mm	MR
	Size of riser/down-comer	02 nos.	02 nos.	
	Number of hydrants per			MR
	floor	02 nos.	02 nos.	
70.00	Hose box per floor     Hose box per floor		1 2 11-4	MR
12.	Yard Hydrants     Total number of hydrants	04 nos.	Provided	MR
		04 nos.	Provided	
10/14	Hose box  Arrangement	L. K.	A 8.7	
13.	Pumping Arrangement Ground level			MR
	- · · · · · · · · · · · · · · · · · · ·	1600 LPM	2400 LPM	MR
T <sub>a</sub>	NAME OF THE PARTY	70 mtr.	70 mtr.	MR
		02 nos.	02 nos.	
	The state of the s	180 LPM	180 LPM	MR
	24 7 7 1000 1000	70 mtr.	70 mtr.	MR
	A 11	1600 LPM	2400 LPM	MR
	Stand by pump output     Stand by pump head	70 mtr.	70 mtr.	MR
	Auto starting/Manual stopping	Required	Provided	MR
	Terrace level			
	Discharge of pump	N/A	900 LPM	N/A
	Head of pump	N/A	40 mtr	N/A
	Power supply	N/A	Provided	N/A
7 ,	Auto starting of pump	N/A	Provided	N/A
14.	Captive Water Storage for Fire	200/303/200	- Victoria de la companya della companya della companya de la companya della comp	
14.	Underground tank     capacity	1,00,000 Ltr	1,40,000 Ltr	MR
	Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead tank capacity	20,000 Ltr	25,000 Ltr	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	1	0	1.77.5
	Pressurization of lift shaf	t N/A	N/A	N/A
	Pressurization of lift lobby	N/A	N/A	N/A
	Communication in lift ca	r Required	Provided	MR
	Fireman's switch	Required	Provided	MR
	Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Required	Provided	
18.	Refuge Area	required	1 Tovided	MR
	Total area location	N/A	NI/A	
19.	Fire Control Room	IVA	N/A	N/A
	Detector system panel	Do! 1	- Table 1	X.
		Required	Provided	MR
15	Tion switch panel	Required	Provided	MR
	PA system panel	Required	Provided	MR

The Indian Newspapers Society, I.N.S. Building, Rafi Marg, New Delhi.

<ul> <li>Battery backup</li> </ul>	Required	Provided	MR
Building floor plan  Special Fire Protection System	Required	Provided	MR MR

\*PNF - Provided but Non-Functional, \*MR - Meeting Requirement, \*NMR - Not Meeting Requirement

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, FSC issued vide letter no. F6/DFS/MS/NDZ/2022/325 dated 25/07/2022, if agreed, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval.

Accordingly, DFA is prepared and put up for perusal and signature please.

Manish Kumar DO (CD)

AS approved FoTo letter is put up for Signature lease

Blakash
08/14/2015