GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/GH/SZ/2025/ 363

Dated: 2 / 05 /2025

FIRE SAFETY CERTIFICATE

Certified that the M/s The JRD Luxury Boutique Hotel (A Unit of JRD Buildcon Pvt. Ltd.) located at B 7/113-A, Safdarjung Enclave, New Delhi - 110029, comprised of Basement + Ground + 03 upper floors: Ground floor - (06 guest rooms), 1st floor - (08 guest rooms), 2nd floor - (08 guest rooms) & 3rd floor - (08 guest rooms) for total 30 guest rooms owned/occupied by JRD Buildcon Pvt. Ltd was granted FSC by this department vide letter No. F.6/DFS/MS/GH/2022/SZ/343 dated 13.07.2022. The building/premises was re-inspected by officer concerned of this department on 09.05.2025 in presence of Mr. I. J. Kapoor (Owner) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. The owner has submitted an affidavit on 14.05.2025 stating not to use any above third floor for any purpose & basement used for incidental storage. Accordingly, the premises is fit for occupancy class (Group-A), "Residential & Lodging", ground floor - (06 guest rooms), 1st floor to 3rd floor - (08 guest rooms at each floor) 31.03.2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to conditions under rule 38 of Delhi Fire service Rules, 2010 subject to conditions printed below.

Issued on 21 65 2025 at New Delhi by

Delhi Fire Service

Tel: 011-23414000

Copy to:-

1. The Commissioner, MCD, Delhi:- with a request to kindly ensure the occupancy as detailed above & deviation, if any. w.r.to ID No. 2025041706604 dated 24.04.2025.

2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New

Delhi.

3. The Licensee, M/s The JRD Luxury Boutique Hotel (A Unit of JRD Buildcon Pvt. Ltd.) at B 7/113-A, Safdarjung Enclave, New Delhi - 110029.

Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub

rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

8. No occupancy used above third floor and basement used for incidental storage purpose only shall be strictly adhered by Owner/occupier.

9. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

10. This FSC is valid for 30 guest rooms from ground to 3rd floor only.

		IN	ISP	PECTION REPO	RT		
1	bui	Name & address of the building M/s The JRD Luxury Boutique Hotel (A Unit of JRD Buildeon Pyt. Ltd.) leasted at B. 7/113 A					
2	Bu	lding is comprised of		(Basement + G	round + 03 upper	10020	
				Dasement - (inc	Cidental storage)	10013)	
				Ground floor -	(06 guest rooms)		
				1 1100r - (()8 p	liest rooms)		
				2 nd floor - (08 g	uest rooms)		
3	Т			3 rd floor – (08 g	uest rooms)		
4	Ty	be of occupancy		Residential "Gro	oup-A" (Guest House	•)	
		be of case		Renewal	-pii (Guest House	.,	
5	De	ails of previous FSC		F.6/DFS/MS/GH	H/2022/SZ/343 dated	13 07 2022	
6	Fir	safety direction letter no		Nil	UZUZZI SZI STS dated	15.07.2022	
7	Da	e of inspection		09.05.2025			
8	Na	me of the inspecti	nσ	ADO (SPM)			
	off	cers	6	ADO (SEM)			
9	Na	ne of the designation	of	Mr. I. J. Kapoor	(Owner)		
	off	cer from the building side	J1	мі. і. ј. Кароог	(Owner)		
10	Ye	ar of construction		2007			
11	_	olicant's letter no.			ID No. 20250417	706604 dated	
	1	o letter no.		24.04.2025	1,0.		
S.No	Mi	nimum Standards on fire		Requirements	Provided at Site	Remarks	
~12 10		evention and fire safety	1	Requirements		MR/	
		uirements U/R 33				NMR	
1	Ac	cess To Building:	-			T	
		ad width	1	2 mtr.	Provided	MR	
	Ga	e width		JA	NA	NA	
	Wi	dth of internal road		JA	NA	NA	
2	Nu	mber, Width, Type and A	rra	angement of Exits	S:		
	A	Number of staircases	1	2 nos.	Provided	MR ·	
		a Upper floor b Basement	+	2 nos.	Provided	MR	
	D	Width of staircases	0.	2 1103.			
	В	a Upper floor	1	.25 mtr.	1.10 m & 1.0 m	MR (old	
		а орры пос		VALUE - 1 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2		case)	
		b Basement	1.	.25 mtr.	1.10 m & 1.0 m	MR (old	
		D i i C i i	-			case)	
	C	Protection of exits	D	equired	Provided	MR	
		a Fire check door b Pressurization		A	NA	NA	
	D	No. of continuous		equired	01 no.	MR	
		staircases to terrace		•			
	E	Width of corridor	5500	5 mtr.	Provided	MR	
		Door size	1.	0 mtr.	1.0 m (final exit)	MR	
	F						
3	-	npartmentation:	_				
3	-	Fire check door		A	NA	NA NA	
3	Co	Fire check door Sealing of electrical	N N		NA NA	NA NA	
3	Co A B	Fire check door Sealing of electrical shafts	N	A	NA		
3	Co A B	Fire check door Sealing of electrical shafts Fire rating of shaft door	N N	A A		NA	
3	Con A B C D F	Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain Fire dampers	N N N	A A A	NA NA NA NA	NA NA	
	Con A B C D F	Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain Fire dampers	N N N	A A A	NA NA NA NA	NA NA NA	
3	Con A B C D F	Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain	N N N As	A A A	NA NA NA NA	NA NA NA	

5.	Fire I	Extinguisher:					
•	A	Total numbers	12 nos.	12 nos.	MR		
}	B	Types	CO ₂ & ABC	Provided	MR		
}	C	ISI marking	Required	Provided	MR		
	C	Aid-Hose Reels:		•			
•		Total numbers of each floor	01 no.	01 no.	MR		
	A	Length of hose reel hose	30 m	30 m	MR		
	В	Nle diameter	05 mm	05 mm	MR		
	Automatic Fire Detection And Alarming System: As per clause 7.31 of UBBL 2016						
7	Auto	matic Fire Detection And 12	Required	Provided	MR		
	A	Type of detectors (CO	Acceptance				
		type) Location of main panel	Required	Provided	MR		
	B	Location of main panel	NA	NA	NA		
	C	Alternate source of power	Required	Provided	MR		
	D	Hooters	Required	Provided	MR		
0	E MOI		Required	Provided	MR		
8			Required	Provided	MR		
9	Publ	ic Address System:		onl.			
10	-	omatic Sprinkler System:	Required	Provided	MR		
	A	Basement	NA	NA	NA		
	В	Upper floor	NA	NA	NA		
	C	Sprinkler above false	INA	, , ,			
2		ceiling			- •		
11	_	rnal Hydrants:	NA	NA	NA		
	A	size of riser/down-comer	NA	NA	NA		
	В	Number of hydrants per	1474				
	C	floor Hose box	NA	NA	NA		
12	100	d Hydrants:	,				
12		Total number of hydrants	NA	NA	NA		
	A	Hose box		NA	NA		
	В		1471				
13	200	nping Arrangements:					
	A	Ground level	NIA	NA	NA		
	a)	Discharge of main pump	NA		NA		
	b)	Head of main pump	NA	NA			
	c)	Number of main pumps	NA	NA	NA		
	d)	Jockey pump out put	NA	NA	NA		
	e)	Jockey pump head	NA	NA	NA		
	f)	Standby pump out put	NA	NA	NA		
	g)	Standby pump head	NA	NA	NA		
	h)	Auto starting /manual	NA	NA	NA		
	i)	stopping Pump house access	NIA	NTA	NIA		
	B	Terrace level	NA	NA	NA		
	a)	Discharge of pump	450 I D) 4	D 11.1	3.00		
	b)	Head of the pump	450 LPM 35 m	Provided	MR		
	c)	Power supply	Required	Provided	MR		
	d)	Auto starting of pump	Required	Provided	MR		
L	_ -/	The state of the s	Keammaa	Provided	MR		

4 Ca	ptive Water Storage For Fire F	ighting:	,			
A	Underground tank capacity	NA	NA	NA		
В	Draw-off connection	NA	NA	NA		
C	Fire service inlet	Required	Provided	MR		
D	Access to tank	NA	NA	NA		
E	Overhead tank capacity	10,000 ltrs.	Provided	MR		
5 Ex	it Signage:	Required	Provided	MR		
6 Pr	Provision of Lifts:					
A	Pressurization of lift shaft	NA	NA	NA		
В	Pressurization of lift lobby	NA	NA	NA		
C	Communication in lift car	NA	NA	NA		
D	Firemen's grounding switch	NA	NA	NA		
E		NA	NA	NA		
	andby Power Supply:	Required	Provided	MR		
	Refuge Area:					
A	Total area	NA	NA	NA NA		
B	Location	NA	NA	NA		
_	re Control Room :			NA		
A	Detector system panel	NA	NA	NA NA		
В	Flow switch panel	NA	NA	NA		
C	•	NA	NA	NA		
D	Battery backup	NA	NA	NA		
E	Building floor plans	NA	NA NA	NA		
20 Si	pecial Fire Protection Systems F	or Protection of	NA			
S.	pecial Risks, If Any:	ere tested, checke	1 of rand			

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

The owner has submitted an affidavit on 14.05.2025 stating not to use any floor above third

floor for any purpose & basement used for incidental storage only.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No F.6/DFS/MS/GH/2022/SZ/343 dated 13.07.2022 is recommended to be renewed for 30 guest rooms upto 3rd floor only, under Rule 37 of the Delhi Fire Service Rules 2010.

> Signature of the Inspecting Officer Sumit Kumar Name ADO (SPM) Designation

Houf Str.

p For Signature, Please. 5.T. Litter is but

Dixetes