## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI – 110001

No. F6/DFS/MS/EH/NDZ/2025/

302

Dated 03 07 2025

To,

The Dy. Health Officer, Karol Bagh Zone, Anand Parbat, New Delhi.

Sub: Inspection report in respect of The Mandi Chowk (A unit of Ashlyn Restaurant LLP), located at P3/90, 1<sup>st</sup> & 2<sup>nd</sup> Floor, Connaught Place, New Delhi-110001.

Sir,

Please refer to your online application ID. No. 2025051808658 dated 04/06/2025, on the subject cited above. In this connection, it is to inform you that the said premise was inspected by the officer concerned of this department on 24/06/2025 in the presence of Sh. Neeraj Tiwari to check the Fire safety arrangements.

During inspection, it was observed that the restaurant is running at 1<sup>st</sup> & 2<sup>nd</sup> Floor, in a building comprised of ground + 02 upper floors. Fire safety arrangements such as fire extinguishers, first-aid hose reel, MOEFA, pumping arrangement & exit signage etc, are provided. However, following shortcomings were observed:-

- 1. Two exits of 2 x 1.5m are provided but one exit is passing through kitchen at second floor.
- 2. First aid hose reel is found removed at 1st floor.
- 3. Internal hydrant is provided but not functional.
- 4. 450 LPM pump is provided but not functional.
- 5. Exit signage are found removed.

In view of above shortcomings, the application for renewal fire safety certificate is not considered at this stage & rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The licensing Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

(Afull Starg

Delhi Fire Service

Copy to: -

1. The Owner/Occupier, The Mandi Chowk (A unit of Ashlyn Restaurant LLP), located at P3/90, 1<sup>st</sup> & 2<sup>nd</sup> Floor, Connaught Place, New Delhi-110001.