

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आज़ादी_{मा} अमृत महोत्सव

No.F6/DFS/MS/Banquet/SZ/2025/38

Dated:

11/06/2025

FIRE SAFETY CERTIFICATE

(Virendra Singh)
Chief Fire Officer

Delhi Fire Service

Reference: etl.mcdonline application ID no. 2025052709201.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The means of escape shall be kept unobstructed/unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

				ECTION REPORT				
			ldress of the building	M/s The Meraki Grand (Banquet Hall) located at A 29, G.T.K. Road, Industrial Area, Delhi-33.				
	Building is comprised of Type of occupancy			Basement + Ground + Mezzanine + 02 upper floors Group D - Assembly Building (Banquet Hall)				
	Type of case		se	Renewal				
	Details of previous FSC			F6/DFS/MS/2022/WZ/BNQT/01 dated 04.01.2022				
H	Fire safety directive letter no.		directive letter no.	F6/DFS/MS/2019/1254 dated 13.03.2019				
	Date of inspection Name of the inspecting officers			05.06.2025				
				Rajesh Kumar Shukla ADO (M. Road)				
			ne designation of officer	Mr. Sanjay Taneja (Manager)				
	From 1	he b	uilding side					
0			nstruction	2006 (As per online application)				
1			s letter no	etl.mcdonline ID no. 2025052709201				
.No	Pr	even	um Standards on fire ation and fire safety ements U/R 33	Requirement as per Rule 35 (6)	Provided at Site	Remarks MR/NMR		
			to Building					
	A		oad width	18.0 mtrs	Provided	MR		
	В	1000	ate width	5.0 m	Provided	MR		
	C		idth of internal road	NA	NA	NA		
-			er, Width, Type and Arran					
	A		mber of staircases		oz i Limoni			
		a	Upper floor	02 nos.	Provided	MR		
	1 1	b	Basement	02 nos.	Provided	MR		
à	B Width of staircases			The state of the s				
		a	Upper floor	2.0 m each	2.0 m each (1 no. Iron staircase)	MR		
		b	Basement	2.0 m each	2.0 m each (1 no. Iron staircase)	MR		
	C	Pro	tection of exits	edelica de vi		1,5		
	Ŭ	a	Fire check door	Required	Provided	MR		
		b	Pressurization	NA	NA	NA		
	D	No	. of continuous staircases terrace	02 nos.	Provided	MR		
	E	80000	dth of corridor	NA	NA	NA		
	F		oor size	2 nos. x 2.0 m	2 nos. x 2.0 m	MR		
Ni .			artmentation	n.M.		1.00		
,	A		re check door	Required	Provided	MR		
	B		aling of electrical shafts	Required	Provided	MR		
	C		re rating of shaft door	2 hours	Provided	MR		
	D		ater curtain	NA Philippin Table and	NA	NA NA		
	E		re dampers	NA .	NA	NA		
	Smoke Management System.			The second second	h. Mad Sprinkshills	l v m		
ji	A Basement			Required	Provided	MR		
	B	135	pper floor	Required	Provided	MR		
_	- 25.00		Extinguisher		ALE THE INC.	15-		
5.	A	_	Total numbers	10 nos.	Provided	MR		
		100		CO ₂ & ABC	CO ₂ & ABC	MR		
	E		Types ISI marking	ISI marked	ISI marked	MR		

,	First-Aid-Hose Reels. 02 nos.			02 nos.	MR				
	A	Total numbers of each floor	30 m	Provided	MR				
	В	Length of hose reel hose		Provided	MR				
	C	Nozzle diameter) iiiii						
7	Aut	omatic Fire Detection And Alarming	Provided	MR					
	A	Type of detectors	Heat/Smoke	Provided	MR				
	B	Location of main panel	Ground	Provided	·MR				
	C	Location of repeater panel	Alternate floor	Provided	MR				
	D	Alternate source of power	Required Required	Provided	MR				
	E Hooters		Required	Provided	MR				
8	MOEFA		Required	Provided	MR				
9	Public Address System.								
10		tomatic Sprinkler System.	Deswind	Provided	MR				
	A	Basement	Required		NA				
	В	Upper floor	NA	NA					
	C	Sprinkler above false ceiling	NA	NA	NA				
11	Internal Hydrants								
ijoj m	A	Size of riser/down-comer	100 mm	Provided	MR				
	В	Number of hydrants per floor	02 nos.	Provided	MR				
	C	Hose box	02 nos.	Provided	MR				
12	Yard Hydrants.								
	A	Total number of hydrants	NA	NA	NA				
	В	Hose box	NA	NA	NA				
13	Pumping Arrangements.								
144	A								
	a)	Discharge of main pump	2280 LPM	Provided	MR				
	b)	Head of main pump	40 m	Provided					
	c)	Number of main pumps	1 no.	3 25 AT A T	MR				
	d)	Jockey pump out put	180 LPM	Provided	MR				
	e)	Jockey pump head		Provided	MR				
	f)	Standby pump out put	40 m	Provided	MR				
	g)	Standby pump head	2280 LPM	Provided	MR				
	h)	Auto starting /manual stopping	40 m	Provided	MR				
	i)	Pump house access	Auto	Provided	MR				
	В	Terrace Level	Required	Provided	MR				
	a)	Discharge of pump	137		must a				
	b)	Head of the pump	900 LPM	Provided	MR				
	c)	Power supply	40 m	Provided	MR				
	d)	Auto starting of pump	Required	Provided	MR				
14	\perp	bump	Required	Provided	MR				
14	Captive Water Storage for Fire Fighting A Underground to the		IVIR IVIR						
4.	_	- "doi giouild lank canacity.			J. LIX				
	B	Draw-off connection	2,00,000 ltrs	Provided	MR				
	C	Fire service inlet	NA	NA	NA				
	D E	Access to tank	Required	Provided	MR				
		Overhead tank capacity	Required	Provided	MR				
	M/s Th	e Meraki Grand (Banquet Hall) loogted	10,000 ltrs	Provided	MR				

Mars The Meraki Grand (Banquet Hall) located at A-29, G.T.K. Road, Industrial Area, Delhi-33.



15	Exit Signage.		Required	Provided			
16	Provision of Lifts.			Trovided	MR		
	A	Pressurization of lift shaft	NA	1374			
	В	Pressurization of lift lobby	NA NA	NA	NA		
	C	Communication in lift car	NA	NA	NA		
	D	Firemen's grounding switch	NA NA	NA	NA		
	E	Lift signage		NA	NA		
17	Standby Power Supply		Required	Provided	MR		
	_		Required	Provided	MR		
18	Refuge Area.						
	A	Total area	NA	NA	NA		
	В	Location	NA	NA	NA NA		
19	Fire Control Room						
	A	Detector system panel	NA	NA	NA		
	В	Flow switch panel	NA	NA	NA NA		
	C	Pa system panel	NA	NA	NA		
	D	Batter backup	NA	NA	NA NA		
	E	Building floor plans	NA	NA	NA NA		
20	Special Fire Protection systems for protection of special Risks, if any:			NA	NA		

<u>LEGENDS:-Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).</u>

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

The shortcomings issued to the Banquet Hall by this department vide letter no.F6/DFS/MS/2025/BNQT/68 dated 24.04.2025 has been rectified by the management.

Keeping in view of the compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/2022/WZ/BNQT/01 dated 04.01.2022 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

M Ja

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

DO (NW)

Dy Co to

1 6/8 /2025

CFO) Muy 6 61 2005

ADO (M.R)