GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

No. F.6/DFS/MS/GH/2025/SZ/ 536

Dated: 06/10/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s. The Meriton a unit of Unique Hospitality LLP located at Okhla, NSIC Metro Station, New Delhi- 110020, building comprised of basement, ground plus 08 upper floors, using basement as parking, ground floor as reception & restaurant, 1st & 2nd floor each having 08 guest rooms, 3rd, 4th, 5th, 7th & 8th floor each having 13 guest rooms respectively & 6th floor having 12 guest rooms guest rooms), was issued FSC by this department vide letter No. F.6/DFS/MS/Residential/2020/SZ/393 dated 01.10.2020 (for residential building). The building was reinspected by the officer concerned of this department on dated 24.09.2025 in the presence of Sh. Vishu Goyal, and found that the guest house have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (93 guest rooms only) is fit for occupancy class "Residential Building" (Sub Division A-5) w.e.f. 06 10 707 valid up to 31.03.2028, in accordance with rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 86 10 2015 at New Delhi.

Dy. Chief Fire Officer South Zone 200

Copy to: -

The Commissioner, MCD, Delhi: with a request to ensure the occupancy as detailed above and deviation, if any. Online application Id 2025062810705 dated 02.09.2025 & Id No. 2025070811115 dated 11.07.2025

The Executive Engineer (Bldg.), MCD, Civic Centre, New Delhi. : - for information regarding use of basement.

Conditions for the validity of fire safety certificate: -

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy

evacuation of occupants in case of an emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. The certificate may not be treated in any case for the regularization of the unauthorized

construction, if any.

7. Basement shall be used as per the BBL/UBBL.

8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building

The Meriton (A unit of Unique Hospitality LLP), located at Okhla

2. Building is comprised of NSIC Metro Station, New Delhi- 110020.

3. Type of Occupancy Basement, ground plus 08 upper floors. Residential

4. Type of Case 5. Details of Previous FSC letter Renewal

F.6/DFS/MS/Residential/2020/SZ/393 dated 01.10.2020 (for 05 years) 6. Fire Safety direction letter No

F.6/DFS/MS/2016/BP/189 dated 12.08.2016 7. Date of Inspection

24.09.2025 8. Name of the Inspecting officers : ADO R.K. Yadav

9. Name and designation of officer

from the building side : Sh. Vishu Goyal 10. Year of construction

: 2020 11 Applicant's letter No

Sr No.	Minimum Standards on Fire Prevention and Fire Safety U/R33	Requirements	Provided at Site	Remarks		
1	Access to Building.	Eco:		MR/NMR		
	F.6/DFS/MS/Residential building vide letter No.					
	Road widthGate widthWidth of internal road	Accessible	12 m			
		4.5 m	5.8 m	MR MR		
		6.0 m	6.0 m	MR		
2	Number, Width, Type and Arrangement o	of Exits.				
	a. Number of Staircases	Common with Metro Station				
	Upper floor	02 No.	02 Nos.	MR		
	Basement	02 Nos.	02 Nos. + 01 ramp	MR		
	B. Width of Staircases			MIX		
	Upper floor	2.0 m & 1.50 m	Provided	MR		
	Basement	2.0 m & 1.50 m	Provided & 01 ramp (2.0 m)			
	c. Protection of Exits		2.0 m)	MIX		
	Fire check door (In Basement)	Required	Provided	MR		
	Pressurization	N/A	N/A	N/A		
	d. No. of Continuous Staircases to Terrace	02 No.	01 No.	MR		
	e. Width of Corridor	2.0 m	2.20 m	MR		
	f. Door Size	1.0 m	Provided	MR		
3	Compartmentation.		1/1 Nf / C/ /			
	Fire check door		mon with Metro Station) (D		
	Sealing of electrical shafts	Required	Provided	MR		
	• Fire rating of shaft door	Required	Sealed	MR		
	• Water curtain	Required	Provided	MR		
	• Fire dampers	Required	Provided	MR		
	Smoke Mon	N/A	N/A	N/A		
	Smoke Management System.					
	• Basement	D	E 1 4 C	MD		
	Innov G	Required	Exhaust fans Natural Ventilation	MR MR		
_	Fire Extinguishers.	Required	ivatural ventilation	IVIIC		
	Total numbers MR					
	Types	60 nos.	Provided	MR		
6	IS marking First-Aid-Hose Reels.	ABC /CO ₂	Provided	MR		
\	Killer	2		MR		

Mzz

07	Automatic Fire Detection, CO detection	n and Alarming System.			
<u> </u>		Required	Provided	MR	
	Type of detectors (CO) Location of main panel	Required	Provided at GF	MR	
	Location of main paner	N/A	N/A	N/A	
	Location of repeater panel	Required	Provided	MR	
	 Alternate source of power Hooter's location 	Each floor	Provided	MR	
	97 WARRANT SANTE	Required	Provided	MR	
08	MOEFA	Required	Provided	MR	
09	Public Address System.	·			
10	Automatic Sprinkler System.	T no mained	Provided	MR	
	Basement & Stilt floor	Required	Provided	MR	
	upper floorsprinkler above false ceiling	Required	N/A	N/A	
		N/A		13/25	
11	Internal Hydrants	Comm	on with Metro Station	\ \m	
	size of riser/down-comer	100 mm	Provided	MR MR	
	Number of hydrants per floor	03	Provided		
	Hose box	03	Provided	MR	
12	Yard Hydrants.				
	Total number of hydrants	03	Provided	MR	
	Hose box	Required	Provided	MR	
13	Pumping Arrangements.				
	> Ground Level	Common with Metro Station			
-	Discharge of main pump				
	Head of main pump	2850 LPM	Provided	MR	
	Number of main pumps	70 m	Provided	MR	
	Jockey pump out put	Two	Provided	MR	
	Jockey pump head	180 LPM	Provided	MR	
	Standby pump out put	70 m	Provided	MR	
	Standby pump head	2850 LPM	Provided	MR	
	Auto starting /manual stopping	70 m	Provided	MR	
	Pump house access	Required	Provided	MR	
-	> Terrace Level				
	Discharge of pump	900 LPM	Provided	MR	
	Head of the pump	40 m	Provided	·	
	Power supply	Required	Provided	MR	
	Auto Starting of pump	Required	Provided	MR MR	
4	Captive Water Storage for Fire Fighting.		- S		
	Underground tank capacity	Common with Metro Station 2,00,000 ltrs. Provided		tation	
	Draw-off connection	Required	Provided	MR	
	Fire service inlet	Required	Provided	MR	
	Access to tank	Required	Provided	MR	
	Overhead Tank capacity	25,000 ltrs.	Provided	MR	
	The state of	23,000 Itrs.	Provided	MR	
5	Exit Signage.	Required	Provided	MIK	
			Danivor	MR	

	Provision of Lifts.		Common with Metro Station				
	Pressurization of Lift Shaft Pressurization of Lift lobby Communication in lift car Firemen's grounding switch Lift Signage	Required	Provided	MR			
7 8		Required	Provided	MR			
		Required	Provided	MR			
		Required	Provided	MR			
		Required	Provided	MR			
	Standby power supply	Required	Provided	MR			
	Refuge Area.						
	A CONTRACT OF THE CONTRACT OF	N/A	N/A	N/A			
	Total area Location	N/A	N/A	N/A			
_	Fire Control Room						
	Detector system panel Flow switch panel PA system panel	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
	Battery backup Building Floor Plans	N/A	N/A	N/A			
	Special Fire Protection systems for protection of special Risks, if any:	Required	CO2 Flooding System Provided	MR			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: - The Residential building was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/Residential/2020/SZ/393 dated 01.10.2020 for the building comprised of basement, ground plus 8th upper floors, now the applicant applied for guest house, using basement as parking, ground floor as reception & restaurant (restaurant having separate FSC by this department vide letter No. F.6/DFS/MS/EH/NDZ/2025/235 dated 16.06.2025) 1st & 2nd floor each having 08 guest rooms, 3rd, 4th, 5th, 7th & 8th floor each having 13 guest rooms respectively & 6th floor having 12 guest rooms only (total 93 guest rooms).

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter No. F.6/DFS/MS/Residential/2020/SZ/393 dated 01.10.2020, is recommended to be renewed under rule 37, of the Delhi Fire Service Rules, 2010.

Signature of the Inspecting Of

Name: - R.K. Yadav

Designation: - ADO (JKP)

DO (SP)

M

Mulyslaho

Principal director

Ofo

10

26/08/21

CF2/