21 04 2025

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001
DFS/MS/GH/NDZ/2025/ 32 | Dated: 08/05/2025

No. F6/DFS/MS/GH/NDZ/2025/ 32 |

(Adul Gar

FIRE SAFETY CERTIFICATE

Certified that M/s. Udhav Palace Guest House, located at Prop. No. 3317 to 3321, Bagichi Habib Bux, Gali Hari Mandir Paharganj, New Delhi, in a building Comprised of Ground + 03 Upper Floors, Ground Floor (reception + 02 guest rooms + 01 office), 1st Floor to 3rd Floors (06 guest rooms at each Floors), (total 20 guest rooms), owned/occupied by M/s. Udhav Palace Guest House, was issued FSC by this department vide letter no. F6/DFS/MS/GH/NDZ/2021/380 dated 13/09/2021. Now, the building/premises was re-inspected by the officer concerned of this department on 02/05/2025 in the presence of Sh. Nandu Bajpai (Caretaker) and found that the said guest house building having given affidavit dated 28/11/2019, regarding not to use any floor above 3rd floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential" Sub Division A-1 Ground Floor (reception + 02 guest rooms + 0)/ office), 1st floor to 3rd floor (06 guest rooms at each floors), (Total 20 guest rooms upto 3rd floor only), validity upto 31/03/2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 18 of the Delhi Fire Service Rules, 2010. Conditions mentioned below.

Issued on oslos/225 at New Delhi by.

Copy to:-

1. The Commissioner, MCD, Civic Centre, New Delhi. to ensure the occupancy as detailed above & deviation if any

2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi. Email Id: (addlep.lic-dl@nic.in)ID No. 2025040905970 dated 09/04/2025

3. The owner/occupier, M/s. Udhav Palace Guest House, located at Prop. No. 3317 to 3321, Bagichi Habib Bux, Gali Hari Mandir Paharganj, New Delhi.

Conditions for the Validity of Fire Safety Certificate:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working
- 2. Any loss of life or property due to non functional fire safety measures shall be at the risk
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation, with regards to construction shall be verified by the concerned building
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. The means of escapes shall be kept unobstructed/unlocked for unhindered evacuation in
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first www.dfs.delhigovt.nic.in 2010. The form available
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to
- 9. This clearance/FSC shall stand canceled if guest gouse owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27/05/2019 & clarification issued on dated 29/06/2021 latest by 30/09/2021.

		D V							
V	Name & address of the 1 www.								
1.	Name & address of the building	M/s. Udhav Palace Guest House, located at Prop. No. 3317 to 3321, Bagichi Habib Bux, Gali Hari Mandir Paharganj, New Delhi.							
2.	Type of Occupancy								
3.	Type of Case	Residential (Sub Division A-1) (Guest House) Renewal							
4.	Details of previous NOC								
5.	Fire Safety directives letter No	F6/DFS/MS/GH/NDZ/2021/380 dated 13/09/2021 Nil							
6.	Date of inspection	02/05/2025							
7.	Name of the Inspecting Officers	Sarabjeet Singh ADO (MN)							
8.	Name and designation of	Sh. Nandu Bajpai (Caretaker)							

Online application ID No.2025040905970 dated 09/04/2025 The said guest house is running at Ground + 03 Upper Floors, in a building comprised of Ground + 03 Upper Floors. Ground Floor (reception + 02 guest rooms + 01 office), 1st to 3rd floors (06 guest rooms at each floors), (total 20 guest rooms), having given Affidavit on dated 28/11/2019 regarding not use any floor above third floor.

2001 (As per online application)

officers from the building side

Year of Construction

10. Applicant's letter No.

0	Minimum Standards on fire prevention and fire safety U/R 33	As per Rule 35 (6) DFS Rule 2010	Provided at site	Remarks MR/NMR	
	Access to building	,			
	 Road width 	NA	03 mtr	NA	
	Gate width	NA	NA	NA	
	 Width of internal road 	NA	NA	NA	
	Number, Width, Type & Arrange	ment of Exits			
	a. Number of staircases				
	Upper Floors	01 Nos.	Provided	MR	
	 Basements 	NA	NA	NA	
	b. Width of staircases				
	Upper Floors	0.80m	1.5m Provided	MR	
	Basements	NA	NA	NA	
	c. Protection of exits				
	 Fire check door 	NA	NA	NA	
	 Pressurization 	NA	NA	NA	
	d. No. of continuous staircases to terr	ace NA	NA	NA	
	e. Width of Corridor	NA	NA	NA	
	f. Door Size	1.0m	1.0 Provided	MR	
3	Compartmentation.		,		
	 Fire check door 	NA	NA	NA	
	 Sealing of electrical shafts 	NA	NA	NA	
	 Fire Rating of shaft door 	NA	NA	NA	
	Water Curtain	NA	NA	NA	
	Fire Dampers	NA	NA	NA	
4	Smoke Management System.	As per	As per clause 7.31 of UBBL 2016		
	Basements	NA	NA	NA	
_	• Upper floors	Required	Provided	MR	
5	8	111			
	Total numbers	08 nos.	08 nos.	MR	
	• Types	CO ₂ , ABC type	Provided	MR	
	IS marking	ISI marked	Provided	MR	

	First-Aid Hose Reels.					
	Total numbers on each floor	01	Provided	MR		
	• Length of hose reel hose	30 m	Provided	MR		
7	Nozzle diameter	05 mm	Provided	MR		
	Automatic fire detection and alarm	ing system.	11011404	IVIK		
	 Type of detectors 	CO	7 7			
	 Location of Main Panel 		Provided	MR		
	 Location of Repeater Panel 	Ground Floor	Provided	MR		
	Alternate source of power	NA	NA	NA		
	Hooters' Location	Required	Provided	MR		
8	MOEFA	Each Floor	Provided	MR		
9		Required	Provided	MR		
	Public Address System.	Required	Provided	MR		
10	Automatic Sprinkler System.	•				
	• Basement	NA	NA NA	NA NA		
	Upper Floor	NA	NA NA	NA NA		
	Sprinkler above false ceiling	NA	NA	NA NA		
11	Internal Hydrants		1			
	Size of riser/down-comer	NA	NA NA	NA NA		
	Number of hydrants per floor	NA	NA NA	NA NA		
	Hose Box	NA NA	NA NA	NA NA		
12	Yard Hydrants.	IIA	INA	IVA		
	Total number of hydrants	NA	NA	NA NA		
	Hose Box	NA NA	NA NA	NA NA		
13	Pumping Arrangements.	1111	1771	1771		
	Ground Level					
	Discharge of main Pump	NA	NA	NA		
	> Head of Main pump	NA NA	NA NA	NA		
	> Number of main pumps	NA	NA	NA		
	> Jockey Pump out put	NA	NA	NA		
	> Jockey pump head	NA	NA	NA		
	➤ Standby Pump out put	NA	NA	NA		
	Standby Pump Head	NA	NA	NA		
	> Auto Starting/ Manual stopping	NA NA	NA	NA		
	> Pump House Access	NA	NA	NA		
	Terrace level➤ Discharge of pump	225 LPM	Provided	MR		
	> Head of the pump	30 mtr	Provided	MR		
	> Power Supply	Required	Provided	MR		
	> Auto Starting of pump	Required	Provided	MR		
14	Captive Water Storage for fire fighting.					
	Underground tank capacity	NA	NA	NA		
	> Draw-off connection	NA ·	NA NA	NA		
	> Fire service inlet	NA NA	NA NA	NA NA		
	 Access to tank Overhead Tank capacity 	2500 Ltrs	Provided	NA MR		
15	Exit Signage.	Required	Provided	MR		

6 Pro	vision of Lifts.	- M24-		
•	Pressurization of Lift Shaft	77.		
•	Pressurization of Lift lobby	NA	NA	NA
	Communication of Lift lobby	NA	NA	NA
	Communication In lift Car	Required	Provided	MR
•	Fireman's Grounding Switch	Required	Provided	MR
•	Lift Signage	Required		
Stan	dby power supply	•	Provided	MR
	ge Area.	Required	Provided	MR
Keru				
	otal Alea	NA	NA	NA
Fire (Control Room	NA	NA	NA
1110			-	
	Detector System Panel	NA	NA	NA
	Tiow Switch Panel	NA	NA	NA
	1 A System Panel	NA	NA	NA
	Batter backup	NA	NA	NA
Specie	Building Floor Plans	NA	NA	NA
Protect	Fire Protection Systems for ion of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were test checked and found functional at the time of inspection. Further shortcoming issued vide letter no. F6/DFS/MS/GH/2025/144 dated 01.04.2025 have been complied.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules, the NOC vide letter no F6/DFS/MS/GH/NDZ/2021/380 dated 13/09/2021, renewal under the rule 35 of the Delhi Fire Service rules 2010 is recommended for approval PI.

" (Mal)

DON'S

Signature of the Inspecting Officer

Name: Sarabjeet Singh

Designation: Assistant Divisional Officer

Sycho (2002)

05/05/25

C.F.0/

Directa) M. 2025

par

}

U blonde