No. F.6/DFS/MS/Motel/2025/SZ/ 397



Dated: 31/07/2025

## FIRE SAFETY CERTIFICATE

Certified that the building of M/s Umrao Hotels & Resorts (P) Ltd, Khasra No. 31/21/2, 31/22, 31/23, 31/24, 31/25, 32/21, 32/22/1, 32/22/2, 32/23/2(min), 37/2/1/2, 37/2/2/2, 37/3/1, 37/9/2/1, 38/1/2, 38/2, 38/3, 38/4/1, 38/4/2, 38/5/1 & 38/5/2 at Village Samalka, New Delhi-110037, comprised of Basement, Ground Floor, First Floor & Second Floor (Owner office only), was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/Motel/2022/SZ/574 dated 16/12/2022. The premise was re-inspected by the officer concerned of this department on 11/07/2025 in the presence of Mr. Rajneesh Bhargav (GM) and found that the said building/premises is fit for occupancy class "Group A Residential" (Motel) with effect from 31/07/2025 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 31 107 /2025 at New Delhi by

Chief Fire Officer Delhi Fire Service

## Copy to: -

The Dy. Health Officer, Municipal Corporation of Delhi, Najafgarh Zone, Najafgarh Dhansa Road, Near Dhansa Bus Stand, New Delhi-110043

2. Authorized Signatory, M/s Umrao Hotels & Resorts (P) Ltd. situated at Khasra No. 31/21/2, 31/22, 31/23, 31/24, 31/25, 32/21, 32/22/1, 32/22/2, 32/23/2(min), 37/2/1/2, 37/2/2/2, 37/3/1, 37/9/2/1, 38/1/2, 38/2, 38/3, 38/4/1, 38/4/2, 38/5/1 & 38/5/2, Village Samalka, Delhi-110037

## Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. Basement shall be used strictly in accordance with the BBL.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- Form 'J' [sub rule (1) of rule37] along with a copy of this certificate, prior to its expiry.

	INSPECTI	ON REPORT				
1	Name & Address of the Building	M/s Umrao Hotels & Resorts (P) Ltd at Khasra No. 31/21/2, 31/22, 31/23, 31/24, 31/25, 32/21, 32/22/1, 32/22/2, 32/23/2(min), 37/2/1/2, 37/2/2/2, 37/3/1, 37/9/2/1, 38/1/2, 38/2, 38/3, 38/4/1, 38/4/2, 38/5/1 & 38/5/2, Village Samalka, New Delhi-110037  Group 'A' Residential (Motel) Building Basement + Ground floor + First & Second				
	Type of Occupancy					
2	Building Comprised of	Basement + G	round floor	+ First d	& Second	
3	Bunessa	floor (Owner o	office only)			
	Type of Case	Renewal				
4	T Deavious IVIC	F.6/DFS/MS/Motel/2022/SZ/574 Dt. 16/12/2022				
5	Pire Safety Directives Letter No	F6/DFS/MS/BP/2006/1712 dated 25/07/2006				
6		F.6/DFS/MS/2019/BP/821 dated 08/02/2019				
7	Date of Inspection	11/07/2025				
8	talana of the Inspecting Utilicers	ADO (SJ)				
8	Name & Designation of Officers	Mr. Rajneesh Bhargav (General Manager)				
9	from the building side	2010				
10	Vear of Construction	2010				
$\frac{10}{11}$	Applicant letter No. / Online ID	No. Nil dated 27/06/2025 received through outdoor diary No. 3177 dated 27/06/2025				
L.L.		The state of the s				
S.	Minimum standards on Fire	Old NOC	100000000000000000000000000000000000000	ded at	Remarks	
No.	Prevention and Fire Safety U/R 33	Requirement	s Si	te	MR/NMR	
1	Access to Building			2 2		
	Road width	09 mtr		) mtr	MR	
	Gate width	05 mtr		5 mtr	MR	
	Width of internal road	N/A	1	V/A	N/A	
2	Number, width, type & arrangement	of exits.				
2	a) Number of Staircase		-1			
	> Upper floors.	08 Nos	08	Nos	MR	
	Basements	09 Nos		Nos	MR	
	b) Width of Staircase	071103	V.	1100	1,111	
	> Upper floors	1.25 mtr	1.18m-1.4	12m	MR (Old case	
	> Basements	1.25 mtr	The second second			
	c) Protection of exits	1,25 ma	1.10111 1.	2111	MR (Old case	
	Fire check door	Required	Dry	ovided	MR	
	> Pressurization	N/A			N/A	
	d) No. of continuous staircase to terrace			N/A		
	e) Width of corridor	Required		4 Nos		
	f) Door size	1.5 mtr		1.5 mtr		
3	/	1m	Pro	ovided	MR	
3	Compartmentation.	-		No. of the last	MR	
	Fire check door.	Required		Provided		
	<ul> <li>Sealing of electrical shafts.</li> </ul>	Required		Provided		
	<ul> <li>Fire rating of shaft door.</li> </ul>	N/A	_	N/A		
	Water curtain	N/A		N/A		
4	Fire dampers.	Required	Pro	Provided		
4.	Smoke Management System.				MR	
	Basement	30 ACPH	Exha	Exhaust Fans		
	Upper Floors	12 ACPH		System	10000	
5.	Fire Extinguishers.		12 ACM NIV SY		- 1 ****	
	Total numbers	30 Nos	1	40 Nos		
	Types	ABC/W.CO <sub>2</sub> /Co				
	ISI Marking	ISI marked		Provided		
6.	First Aid Hose Reels.	151 marked	110	Tidou	MR	
		/ Non	Dro	vided	MR	
	• Total numbers on each floor.	4 Nos		vided	MR	
	• Length of hose-reel hose.	36m	The state of the s	vided	MR	
	<ul> <li>Nozzle Diameter</li> </ul>	5mm	FIO	,1000		

M.

N-30

7	Automatic fire detection & alarming system.					
	Type of detectors	Smoke & Heat	Smoke & Heat	N/A		
11	<ul> <li>Location of Main Panel</li> </ul>	N/A	Basement	N/A		
	Location of Repeater Panel	N/A	N/A	MR		
	Alternate source of power	Required	Provided	MR		
	Hooter's location	All Floors	Provided	die dries		
8	MOEFA	Required	Provided	MR		
9	Public Address System	Required	Provided	MR		
10	Automatic Sprinkler System			MR		
	Basement.	Required Provided		MR		
	Upper floors.	Required	Provided	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants.	11		1 m		
	Size of Riser/Down-comer	100 mm	Provided	MR MR		
	Number of Hydrant per floor	4 Nos	Provided	MR		
	Hose box.	4 Nos	Provided	IVIIC		
12	Yard Hydrants.		7 11.4	MR		
	<ul> <li>Total number of hydrants.</li> </ul>	4 Nos	Provided	MR		
	Hose box.	4 Nos	Provided	IVIIC		
13	Pumping arrangements.					
	Ground Level	1620 LPM	1620 LPM	MR		
	> Discharge of main pump.	56 mtr	56 mtr	MR		
	<ul><li>Head of main pump.</li><li>Number of main pumps.</li></ul>	1 Nos	1 Nos	MR		
	> Jockey Pump output.	180 LPM	180 LPM	MR		
	> Jockey Pump head.	56 mtr	56 mtr 2280 LPM	MR MR		
	➤ Standby Pump output.	1620 LPM 56 mtr	56 mtr	MR		
	> Standby Pump head.	Required	Provided	MR		
	<ul><li>Auto Starting/Manual Stopping.</li><li>Pump house access.</li></ul>	Required	Provided	MR		
	Terrace Level					
	Discharge of pump.	Required	900 LPM	MR		
	➤ Head of pump.	Required	35m	MR		
	➤ Power supply.	Required	Provided	MR		
	> Auto starting of pump.	Required	Provided	MR		
14	Captive water storage for firefighting.		1.00.000 T			
	Underground tank capacity.	1,00,000 Ltrs	1,00,000 Ltrs	MR		
	> Draw-off connection.	Required	Provided	MR		
	> Fire Service Inlet.	Required	Provided	MR		
	> Access to tank.	Required	Provided	MR		
	Overhead tank capacity.	10,000 Ltrs	10,000 Ltrs	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.	NIA	27/4			
	<ul> <li>Pressurization of lift shaft.</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Pressurization of lift lobby.</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Communication in lift car.</li> </ul>	Required	Provided	MR		
	<ul> <li>Fireman's switch.</li> </ul>	Required	Provided	MR		
	<ul> <li>Lift signage.</li> </ul>	Required	Provided	MR		
17	Standby Power Supply	Required	Provided	MR		
18	Refuge Area					
18	Total area	N/A	N/A	N/A		
	• Location	N/A	N/A	N/A		

N-40

19.	Fire Control Room.			
17.	Detector system panel.     Flow switch panel.	N/A	Provided	N/A
		N/A	N/A	N/A
		Required	Provided	MR
	PA system panel.	Required	Provided	MR
	Battery backup.  Battery backup.  Battery backup.	N/A	N/A	N/A
20.	<ul> <li>Building floor plan.</li> <li>Special Fire Protection System for Protection of Special Risk, if any.</li> </ul>	N/A	CO <sub>2</sub> Fire extinguisher provided near elect. panels	N/A

The fire protection systems provided in the premises were checked, tested at random and found functional at the of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F.6/DFS/MS/Motel/2022/SZ/574 dated 16/12/2022, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

DO (SD)

Mare 16/3/48

cfo

12 71 2025

Principal Director

CFO Dom

Jan tors at

hos level

2703/2

24 71 2015

ADO (58)

287/2V

P. T-D