GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2025/ 461

Dated: 31 /07/2025

FIRE SAFETY CERTIFICATE

Certified that the Unique International Guest House located at 902, Gali Chandi Wali, Main Bazar, Pahar Ganj, New Delhi comprised of Ground floor & 04 Upper floors, Ground (Reception + 02 guest rooms), 1st floor to 3rd floor (04 guest rooms at each floor) & 4th floor not in use as per Affidavit dated 23/11/2019 owned/occupied by Unique International Guest House was granted FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2019/592 dated 22/03/2019. The premises was inspected by the officer concerned of this department on 08/07/2025 in the presence of Sh. Anil Kumar (Owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 for Ground (Reception + 02 guest rooms), 1st floor to 3rd floor (04 guest rooms at each floor) total 14 guest rooms only with effect from 31 67 225 for period of three years, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 3107 2025 at New Delhi by.

(Virendra Singh)
Chief Fire Officer
Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: with a request to ensure the occupancy as detailed above & deviation if any.
- 2. Online id no. 2025032004098 dated 29/06/25.
- 3. M/s Unique International Guest House located at 902, Gali Chandi Wali, Main Bazar, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provide/d in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the MCD Portal along with a copy of this Certificate, six months prior to its expiry".
- 9. This Fire Safety Certificate is valid for ground & 03 upper floors with 14 guest rooms only. In case of any violation, this FSC will be treated as null & void.
- 10. Any flammable material for interior decoration is prohibited.

INSPECTION REPORT Unique International Guest House at 902, 1. Name & address of the building:-Gali Chandiwali, Main Bazar, Pahar Ganj, Residential, Sub Division-A-1 2. Type of occupancy:-Gr. + 04 Upper floors (total 14 Guest rooms) Ground (Reception + 02 guest rooms), 1st floor to 3rd floor (04 guest rooms at each floor) and 4th floor not in use as per affidavit dated 23.11.2019. 3. Type of case:-No. F6/DFS/MS/GH/NDZ/2019/592 dated 4. Details of previous FSC:-22/03/2019. N/A 5. Fire safety directives No.-08/07/2025 6. Date of inspection:-ADO (RN) 7. Name of the inspecting officer:-8. Name & designation of officer Sh. Anil Kumar (Owner) From the building side:-2007 9. Year of construction:-Online ID No- 2025032004098 dated 29/06/25 10. Applicant's letter No:-Remarks Requirement Provided at site Minimum Standards on fire MR/NMR Existing fire Prevention and fire safety safety arrangements Access to Building 1. N/A 2 mtr. N/A 1) Road width N/A N/A N/A 2) Gate width N/A N/A N/A 3)Width of internal road Number, Width Type & Arrangement of Exits 2. A. Number of staircases MR 01 Nos. 01 Nos. 1. Upper floors N/A N/A N/A 2. Basements B. Width of staircase MR 1.13 mtr. 0.80 mtr. 1. Upper floors N/A N/A N/A 2. Basements C. Protection of exits N/A N/A N/A 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous staircase to terrace N/A N/A N/A E. Width of corridor MR 1 mtr. 1 mtr. F. Door size Compartmentation 3. N/A N/A N/A 1) Fire check door N/A N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers Smoke Management System 4. N/A N/A NA 1) Basements Provided MR Required 2) Upper floors Fire Extinguishers 5. MR 08 Nos. 1) Total numbers 08 Nos. ABC & CO2 MR ABC & CO2 2) Types MR Provided Required 3) ISI marking First-Aid Hose Reel 6. 1) Total number of eachfloor 01 01 MR 30 mtr. 2) Length of hose reel hose 30 mtr. MR 05 mm MR 3) Nozzle diameter 05 mm **Automatic Fire Detection & Alarming System** 7. 1) Type of detectors CO Required Provided MR 2) Location of main panel Required Provided MR 3) Location of repeater panel MR N/A Provided 4) Alternate source of power MR Provided Required MR

Provided

Required

5) Hooter's Location

	I MORRE	N/23	Γ		
8.	MOEFA	N/A	Provided	N/A	
9.	Public Address System	N/A	N/A	N/A	
10.	Automatic Sprinkler Sys				
	1) Basement	N/A	N/A	N/A	
	2) Upper floors	N/A	N/A	N/A	
	3) Sprinkler above false	N/A	N/A	N/A	
	ceiling				
11.	Internal Hydrants	**			
	1) Size of riser/down-come	r N/A	N/A	N/A	
	2) Number of hydrants per	N/A	N/A	N/A	
	floor	^			
	3) Hose box	N/A	N/A	N/A	
12.	Yard Hydrants				
	1) Total number of hydrants	s N/A	N/A	N/A	
	2) Hose box	N/A	N/A	N/A	
10		1	1		
13.	Pumping Arrangement			11	
	Ground level	N/A	N/A	N/A	
	a) Discharge of main	N/A	N/A	N/A	
	pump				
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main	N/A	N/A	N/A	
	pump				
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump	N/A	N/A	N/A	
	output		0 1		
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto	N/A	N/A	N/A	
	starting/Manual		.1		
	stopping	Y			
	2) Terrace level				
	a) Discharge of pump	450 LPM	450 LPM	MR	
	b) Head of pump	30 mtr.	30 mtr.	MR	
	c) Power supply	Required	Provided	MR	
	d) Auto starting of	Required	Provided	MR	
	pump	9 <u>4</u> 2			
4.	Captive Water Storage for I	ire Fighting			
1	Under ground tank	N/A	N/A	N/A	
	capacity	La			
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	c) Access to tank	N/A	N/A	N/A	
74	d) Over head tank	2500 LTR	Provided	MR	
	capacity				
5.	Exit Signage	Required	Provided	MR	
	Single Control of the				
6.	Provision of Lifts.		27/4	N/A	
	a) Pressurization of lift	N/A	N/A	IN/A	
	shaft		27/4	N/A	
	b) Pressurization of lift	N/A	N/A	IN/A	
	lobby.		27/4	N/A	
	c) Communication in	N/A	N/A	IN/A	
	lift car			N/A	
-	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	N/A	N/A	N/A	
	Stand by Power Supply	Required	Provided	MR	
		N/A	N/A	N/A	
	Refuge Area			N/A	
		3 T / A	1 N1/ /N	3040 SENSON TO	
	Total area location	N/A	N/A		

19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
-	b) Flow switch panel	N/A	N/A	N/A
450	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
-	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special			
20.	Risk, if any:			

The fire protection systems provided in the building were tested/ checked and found in working order at the time of inspection. The observations/ shortcomings issued and communicated vide this department letter of even no. F6/DFS/MS/GH/NDZ/2022/675 dated: 10/08/2022 have been complied by the management.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate issued vide this department letter of even no. F6/DFS/MS/GH/NDZ/2019/592 dated 22/03/2019 under rule 37 of the Delhi Fire Service Rules 2010. Is recommended for approval up to third floor.

Signature of the Inspecting Officer
Name: - C.L. Meena
Designation: Asst. Div. Officer (RN)

DOCC

1117125

Dyces (2002)

C.FO

" o lifest

senectar Mill

May 1

As approved, F.T. letter is Putup for your signature Pl,

cFol

PTO

14/07/2025 ADO(RN)