

No. F.6/DFS/MS/School/2025/SZ 92

Dated: 30/01/2025

FIRE SAFETY CERTIFICATE

Certified that the Unique Montessori Public School running at ground & first floor only in a building comprised of ground plus two upper floors located at D-17, Durga Vihar, Phase-II, Deenpur, Najafgarh, New Delhi-110043, owned/occupied Unique Montessori Public School was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2021/SZ/1079 dated 27.12.2021. The school building was re- inspected by the officer concerned of this department on 27.01.2025 in the presence of Sh. Pankaj (Manager) and found that the school management have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 issued by the Director of Education and that the building/ premises (ground and first floor only) is fit for occupancy class "Educational Building" w.e.f. 30 01 2025 for a period of three years, subject to compliance of the conditions printed as under.

Issued on 30 01 2025 at New Delhi by.

Director Delhi Fire Service

Copy to: -

- 1. The Manager, Unique Montessori Public School at D-17, Durga Vihar, Phase-II, Deenpur Najafgarh, New Delhi-110043.
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi- 110054.

Conditions for the validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

NIB

INSPECTION REPORT

1. Name & address of the building : Unique Montessori Public School, D-17, Durga Vihar, Phase-II, Deenpur

Najafgarh, New Delhi-110043

2. Building is comprised of : Ground plus two upper floors but school running at ground plus one

upper floor only.

3. Type of Occupancy : Educational
4. Type of Case : Renewal

5. Details of Previous NOC : F.6/DFS/MS/School/2021/SZ/1079 dated 27.12.2021

6. Fire \$afety directives letter No : F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

7. Date of inspection : 27.01.2025
8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Sh. Pankaj (Manager)

10. Year of Construction : 2004

11. Applicant's letter No. : Online email Id pankaibm.3656@gmail.com dated 30.11.2024

S. No.		mum Standards on fire ention and fire safety U/R 33	Requirement as per FSC dt. 27.12.2021	Provided at site	Remarks MR/NMR			
1.	Acce	Access to building						
	•	Road width Gate width Width of internal road	Accessible N/A N/A	05 m N/A N/A	MR, being old cas N/A N/A			
2.	Number, Width, Type & Arrangement of Exits							
	a. Nu	mber of staircases						
_	•	Upper Floors	02 No.'s	02 No.'s	MR			
	•	Basements	N/A	N/A	N/A			
-	b. Width of staircases							
	•	Upper Floor	1.50 & .75 m	1.50 & 1.20 m	MR			
	•	Basements	N/A	N/A	N/A			
	c. Protection of exits		N/A	N/A	N/A			
	•	Fire check door	N/A	N/A	N/A			
		Pressurization			I III			
	d. No. of continuous staircases to terrace e. Width of Corridor		N/A	N/A	N/A			
			N/A	N/A	N/A			
	f. Do	or Size	1.0 m	1.0 m	MR, students are less than 45 in each class room			
3.	Comp	artmentation	AP .		10011			
	•	Fire check door	N/A	N/A	N/A			
1	٠	Sealing of electrical shafts	N/A	N/A	N/A			
	•	Fire Rating of shaft door Water Curtain	N/A	N/A	N/A			
		Fire Dampers	N/A	N/A	N/A			
			N/A	N/A	N/A			
1.	Smoke Management System							
	•	Basements	N/A	N/A	N/A			
	S	Upper floors	Required	Natural Ventilation provided	MR			
•	Fire Extinguishers							
	•	Total numbers	04 No's	08 no.'s provided	MR			
	•	Types	ABC/CO ₂ type	Provided	MR			
	•	IS marking	ISI marked	JSI marked	MR			

NIIA

6.	First-Aid Hose Reels					
-		N/A	N/A	N/A		
	Total numbers on each floor Length of been real bore	N/A	N/A	N/A		
	Length of hose reel hose Nozzle diameter	N/A	N/A	N/A		
7.	Automatic fire detection and alarming system					
	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
8.	MOEFA	N/A	N/A	N/A		
9.	Public Address System	N/A	Provided	MR		
10.	Automatic Sprinkler System					
	Basement	N/A	N/A	N/A		
	Ground Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants					
	Size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12.	Yard Hydrants					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements					
	Ground Level					
	 Discharge of main Pump 	N/A	N/A	N/A		
	➤ Head of Main pump	N/A	N/A	N/A		
	➤ Number of main pumps	N/A	N/A	N/A		
	➤ Jockey Pump out put	N/A	N/A	N/A		
	➤ Jockey pump head	N/A	N/A	N/A		
	➤ Standby Pump out put	N/A	N/A	N/A		
	> Standby Pump Head	N/A	N/A	N/A		
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A		
	➤ Pump House Access	N/A	N/A	N/A		
	Terrace level	IVA	IV/A	N/A		
	➤ Discharge of pump	N/A	N/A	N/A		
	➤ Head of the pump	N/A	N/A	N/A		
	➤ Power Supply	N/A	N/A	N/A		
	➤ Auto Starting of pump	N/A	N/A	N/A		
4.	Captive Water Storage for fire fighting	l e e e e e e e e e e e e e e e e e e e	-			
	Underground tank capacity	N/A	N/A	N/A		
	▶ Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	N/A	N/A	N/A		
i.	Exit Signage.	N/A	N/A	N/A		
i.	Provision of Lifts. (N					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
- 1	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	 Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A		
	- Litt Signage	N/A	N/A	N/A		

MIS

17.	Standby power supply	N/A	N/A	N/A		
18.	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19,	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	 Building Floor Plans 	N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC was issued vide letter no. F.6/DFS/MS/School/2021/SZ/1079 dated 27.12.2021, in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting

Name: - R.K. Yadav Designation: - ADO (JKP)

DO (South West)

28/1/28

Denet