

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No F.6/DFS/MS/2025/WZ/ 549

Dated: 08 // 0 /2025

FIRE SAFETY CERTIFICATE

Certified that the "Unity One" Multi-Level Car Parking located at Rohini (West), Sector-10, Rohini, Delhi comprised of Basement + Ground + 06 upper floors owned/ occupied by Unity Build well Pvt.Ltd. was granted Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/2022/454 dated 12.10.2022. The premises was re-inspected by the officers concerned of this department on 24.09.2025 in the presence of Mr. Sunil K Jain (Vice President) and found that the building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010. and premises is fit for occupancy Mixed (Mercantile & Assembly) building with effect from 08/10/2025 for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 08/10/2095 at New Delhi by

M. K Chattopadhyay Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

1. Mr. Sunil K Jain (Vice President), M/s Unity Build well Ltd., G-3, Ground floor, Aggarwal Corporate Tower, 23, Rajendra Place, Delhi- 110008.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry". 7. The owner / occupier shall submit a declaration every year in form "K" provided in the

schedule of Delhi Fire Service Rules 2010. The form is available on <u>WWW.dfs.Delhigovt.nic.in</u> 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

N/38 INSPECTION REPORT Name & address of the building : Unity One, Multi-Level Car Parking, Rohini (West), Sector-10, Rohini, Delhi-110085 Rohini, Delhi-110085. Type of Occupancy : Assembly & Mercantile Type of Case : Renewal (Basement + Gr.+ 06 upper floors) Details of previous NOC : F6/DFS/MS/2022/454 dated 12.10.2022 Fire Safety directives letter No : F.6/DFS/MS/BP/2014/50 Dated 06.02.2014 Date of inspection Name of the Inspecting Officers : A. K. Sharma, ADO (Rohini) : 24.09.2025 Name and designation of officers from the building side : Sh. Sunil K Jain (Vice President) 9. Year of Construction : 2014 10. Applicant's letter No. : OD No.5955 dated 15.09.2025. Minimum Standards on fire prevention NBC/BBL Provided at site Remarks and fire safety U/R 33 MR/NMR Requirement Access to building 40m 40m MR Road width MR 6.0m 6m Gate width Width of internal road MR Provided 6.0m Width, Type & Arrangement of Exits

1	Number, Width, Type & Arrangement of a. Number of staircases a. Floors	04nos.	04nos.	MR
Ì	a. Number of state Upper Floors		1 ramp	MR
	• Upper Floors	1 ramp	Tamp	
	Basements Width of staircases	1.50mx 02 2.00m x 02 & 1	Provided	MR
	• Upper Floors	ramp 1ramp	Provided, 5.5 m	MR
	Basements Protection of exits Fire check door Pressurization No. of continuous staircases to terrace Width of Corridor Door Size	Required Required 02nosNA- 2m each	Provided provided 02nosNA- Provided Provided	MR MR MR -NA- MR
_	Compartmentation.	Required	80.000	MR
	Fire check door	Required	Provided	-NA-
	Sealing of electrical shafts	-NA-	-NA-	-NA-
	Fire Rating of shaft door	-NA-	-NA-	-NA-
	Water Curtain	-NA-	-NA-	
	Fire Dampers System		Exhaust fan	MR
l	Smoke Management System.	30 a/c per hour		MR
	Basements Upper floors	12 a/c per hour	Natural Ventilated	, IVAC
	15000	#	70nos	MR
5	Fire Extinguishers • Total numbers	70nos		MR
		Wco2/Co2	Wco2 -40/DCP -30	MR
	Types ISI marking	Yes	Yes	17113
6	First-Aid Hose Reels.	Provided	MR	
	Total numbers on each floor	04 at each floor	30m	MR
	Length of hose reel hose	30 m		MR
	Nozzle diameter	5mm	5mm	(910-3)
7	Automatic fire detection and alarming system.		Provided	MR
	Type of detectors	Required	Provided	MR
	Location of Main Panel	Required	Provided	MR
	Location of Repeater Panel	Required Each floor	LIOVIDED	2
V	Alternate source of nouver	Required	Provided	MR

		Allos		
	Hooters' Location	N 39		MR
8	MOEFA	Common areas	Provided	MR
9	Public Address System.		Provided	MR
10	Automatic Sprinkler System. Basement	Required Required	provided	
	Basement	Required	piovia	NA
	Upper Floor	Required	Provided	MR
	• Sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants	Required	Provided	
		•		MR
	Size of riser/down-comer Number of the company of the com	100mm	100mm	MR_
	Number of hydrants per floor Hose Box	04nos.	04nos.	MR
12	Yard Hydrants.	04nos.	04nos.	
		5		MR
	 Total number of hydrants Hose Box 	Required	Provided	MR
13	Pumping Arrangements.	Required	Provided	- IVIIX
	Ping All rangements.			
	Ground Level		THE PLANE	MR
	Discharge of main Pump	2850 lpm	2850 lpm	MR
	riead of Main pump	65m	65m	MR
	Number of main pumps	2850 lpm x 02 & 1800 lpm	Provided	
	Jockey Pump out put	180 lpm x02	180 lpm x02	MR
	Jockey pump head	65m	65m	MR
	Standby Pump out put			MR
	Standby Pump Head	2850lpm .	2850 lpm 65m	MR
	➤ Auto Starting/ Manual stopping	65m	Provided	MR
	> Pump House Access	Required	Provided	
	Terrace level		0001	MR
	Discharge of pump Head of the pump	900 lpm	900 lpm	MR
	➤ Head of the pump➤ Power Supply	40m Required	40m Provided	MR
	> Auto Starting of pump	Required	Provided	MR
4	SCHOOL BOUNDARY BOUNDARY	Required	Tiovided	THE CONTRACTOR OF THE CONTRACT
4	Captive Water Storage for fire fighting. Underground tank capacity	1,00,000 ltr	1,00,000 ltr	MR
	> Draw-off connection	Required	Provided	MR
	> Fire service inlet	Required	Provided	MR
	> Access to tank	Required	Provided	
	Overhead Tank capacity	10,000 ltr	10,000 ltrs	MR
		Required	Provided	MR
5	Exit Signage.	Manou	11011404	MR
6	Provision of Lifts.	Required	Provided	MR
	Pressurization of Lift Shaft Pressurization of Lift Inhy	Required	Provided	
	Pressurization of Lift lobby	Required	Provided	MR
	Communication In lift Car Convending Switch	-NA-	-NA-	MR
	Fireman's Grounding Switch	Required	Provided	-NA-
	Lift Signage	Required	Provided	MR
7	Standby power supply	Manag		MR
8	Refuge Area.	-NA-	-NA-	
	> Total Area	-NA-	-NA-	-NA-
	> Location	2.000	2007.7	-NA-
9	Fire Control Room	Required	Provided	7. 44
,	Detector System Panel	Required	Provided	MR
	Flow Switch Panel	Required	Provided	MR
	PA System Panel	Required	Provided	MR
	Datter hackup	Required	Provided	MR
	Building Floor Plans	W. Salar		MR

7/	N/40					
Special Fire Protection of spe	tection Systems for ecial Risks, if any:	-NA-	-NA-	-NA-		
Accordingly, to	he fire protection systems p ition at the time of inspection	rovided in the buildi	ng were tested/ che	cked randomly and		
In view of the	deemed compliance of the noder the rules the FSC issue ewal of FSC under rule 37 of		NTC/NAC/3033/14E4 3	ion and fire safety lated 12.10.2022 is		
· recours			Jul 2514	124		
۸/4		Nan	nature of the Inspect ne: - Ajay Kumar Signation:- ADO/Ro	ting Officer Sharma		
DO (NW) - N/A	á					
Dy. CFO (WZ)	26/8	*				
6/09/25	1 Mugh					
Pri	26 91 Jord neipal Dinector	D-	1. CFD to	Serve.		
	D		4)		
	2	p. C170	œ			
		0				
	A 100	pohini)				
	FT let	te is for	t up	or Kin		
	Perusal and	Lignali	u pens			
	Den	.h	Aud			
	MScel	9	4	1/10/25		