

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001



No F.6/DFS /MS/2025/WZ/ 594

Dated 06 / 11 /2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Upaj Buildcon Pvt. Ltd. located at Plot No-1B1, Twin District Centre, Sector-10, Rohini, Delhi-110085, comprised of 03 Tier Basement, Ground & 09 upper floors only owned/ occupied by M/s Upaj Buildcon Pvt. Ltd. was granted Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/2022/WZ/593 dated 28/12/2022. The premises was inspected by the officers concerned of this department on dated 25/10/2025 in the presence of Sh. Vijay (Mall Manager) and observed that all the fire prevention and fire safety arrangements as provided found in good working condition and the premises have deemed complied with the requirements under Rule 33 of the Delhi Fire Service Rules, 2010 and building premises is fit for occupancy class "Mercantile/Business and Parking" with effect from.

Issued on ...06 !!! 2022 at New Delhi by.

Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

1. The Authorized Signatory, M/s Upaj Buildcon Pvt. Ltd. located at Plot No-1B1, Twin District Centre, Sector-10, Rohini, Delhi-110085

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape shall be kept free from any type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipment and method

of smooth and speedy safe evacuation of occupants in case of emergency

All the fire safety arrangements provided therein shall be maintained in good working condition at all
time as seem during inspection. Any loss of life or property due to non-functional fire safety measures
shall be at the responsibility of the management.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities. This Fire Safety Certificate is valid only for permanent

building structure as per plan.

5. This fire safety certificate may not be treated in any case of regularizations of unauthorized construction/unauthorized use of land or activities, if any.

6. Basement shall not be used for any other purpose except as specified in UBBL, subject to permission from concerned local authority.

7. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on the official website of Delhi Fire Service i.e. www.dfs.delhigovt.nic.in.

8. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J'

[sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

3

INSPECTION REPORT

M/S Upaj Buildcon Pvt Ltd. at Plot No- 1, B-1, Twin District 1. Name & address of the building:

Centre, Sector-10 Rohini, Delhi-110085

Mercantile/Business and Parking 2. Type of Occupancy Renewal

3. Type of Case 3 Tier Basement, Ground & 09 upper floors 4. Composition of building F.6/DFS/MS/2022/WZ/593 dated 28/12/2022 5. Details of Previous FSC F.6/DFS/BP/2006/1473 dated 04.07.2006

6. Fire Safety directives letter No 25/10/2025

C.L. Meena (ADO/Rohini) & A.K. Jaiswal (DO/NW) 7. Date of inspection 8. Name of Inspecting Officer

9. Name and designation of officers Sh. Vijay (Mall Manager)

From the building side 2006

	N. Cimimu	's letter No. : Letter No. m Standards on fire prevention	NBC Requirement	Provided at site	Remarks MR/NMF		
	and fire safety U/R 33						
$\overline{}$	Access t	o building	18m	Provided	MR		
-		Road width	NA NA	NA	NA		
c	55	Gate width	Controlled drawings	_	MR		
	• 1	Width of internal road	Exits				
2.	Number	, Width, Type & Arrangement of l	JANG -				
		per of staircases	04	04	MR		
1	•	Upper Floors Basements	07 from 3 rd basement to 1 st basement & 05 form 1 st basement to ground floor	Provided	MR		
				4	1 10		
		of staircases Upper Floor	02nos 1.5m 02nos1.25m	Provided	MR		
		Basements	03nos 1.5m 04nos1.25m	Provided	MR		
			0411037 1120				
	c. Prote	ction of exits	Required	Provided	MR		
		Fire check door	2000	Provided	MR		
	•]	Pressurization	Required		MR		
	d No.	of continuous staircases to terrace	Required	Provided	MR		
		th of Corridor	1.50m	Provided	MR		
		or Size	01m	01m	IVIX		
3.							
3.		rtmentation	Required	Provided	MR		
		Fire check door	Required	Provided	MR		
		Sealing of electrical shafts Fire Rating of shaft door	Required	Provided	MR		
		Water Curtain	Required	Provided	MR		
		Fire Dampers	Required	Provided	MR		
4.	C1	M	Requires				
7.	Smoke Management System			Exhaust fan	MR		
	•	Basements	30 a/c per hour	Provided	MR		
	•	Upper floors	12 a/c per hour	Provided			
5.	Fire Extinguishers				MR		
	•	Total numbers	140nos.	145nos.	MR		
1	•	Types	ABC/CO2	ABC/CO2	MR		
	1.	IS marking	ISI marked	Yes			

	 Total numbers on each floor Length of hose reel hose 	03nos.	Provided	1 (10)			
7000			FIUVIUCU	MR			
		20mm	Provided	N			
	 Nozzle diameter 	6.5mm	Provided	MR			
	Automatic fire detection and alarming system						
	Type of detectors	Heat & smoke	Provided	MR			
	 Location of Main Panel 	Ground floor	Provided	MR			
	 Location of Repeater Panel 	At each floor	Provided	MR			
	Alternate source of power	Required	Provided	MR			
	Hooters' Location	Common area	Provided	MR			
	MOEFA	Required	Provided	MR			
9)	Public Address System	Required	Provided	MR			
).	Automatic Sprinkler System			100			
	Basement	Required	Provided	MR			
	Ground & Upper Floors	Required	Provided	MR			
	Sprinkler above false ceiling	Required	Provided	MR			
1.	Internal Hydrants	4.70	Described	MR			
	Size of riser/down-comer	150mm	Provided 03	MR			
	 Number of hydrants per floor Hose Box 	03	Provided	MR			
	(4) JET MEZ STYTON MONTHAN VERY STYLE	03	Fiovided	41445			
2.	Yard Hydrants Total number of hydrants	04	Provided	MR			
	 Total number of hydrants Hose Box 	04	Provided	MR			
3.	Pumping Arrangements		19 (19 (19 (19 (19 (19 (19 (19 (19 (19 (
<i>y</i> .	Ground Level						
	➤ Discharge of main Pump	2850lpm	Provided	MR			
	> Head of Main pump	110mtrs	Provided	MR			
	> Number of main pumps	05	Provided	MR			
	Jockey Pump out put	180lpm	Provided	MR			
	Jockey pump head	180mtrs	Provided	MR			
	Standby Pump out put	2850lpm	Provided	MR			
	> Standby Pump Head	110mtrs	Provided	MR			
	> Auto Starting/Manual Stopping	Required	Provided	MR			
	> Pump House Access	Required	Provided	MR			
	Terrace level						
	Discharge of pump	900lpm	Provided	MR			
	> Head of the pump	100mtrs	Provided	MR			
	Power SupplyAuto Starting of pump	NA Paradad	Provided Provided	MR MR			
10		Required	Provided	MIK			
4.	Captive Water Storage for fire fighting	2lac	Provided	MR			
	 Underground tank capacity Draw-off connection 	Required	Provided	MR			
	> Fire service inlet	Required	Provided	MR			
	> Access to tank	Required	Provided	MR			
	Overhead Tank capacity	20,000ltr	Provided	MR			
5.	Exit Signage.	Required	Provided	MR			
j. j.	Provision of Lifts.						
	Pressurization of Lift Shaft	Required	Provided	MR			
	Pressurization of Lift lobby	Required	Provided	MR			
	 Communication In lift Car 	Required	Provided	MR			
	 Fireman's Grounding Switch 	Required	Provided	MR			
	 Lift Signage 	Required	Provided	MR			
		^	(2.6.2014938)	IVIN			
		4 6					
	2	5.00					

1	Standby power supply	Required	Provided	MR			
17.	Refuge Area.						
18.	> Total Area	Required at 4 th & 6 th floor	Provided	MR			
	Location	Required	Provided	MR			
).	Fire Control Room						
	Detector System Panel	Required	Provided at GF	MR			
	Flow Switch Panel	Required	Provided	MR			
	PA System Panel	Required	Provided	MR			
	Battery backup	Required	Provided	MR			
	Building Floor Plans	Required	Provided	MR			
	Special Fire Protection System for Protection of special Risks, if any:	Gas flooding for H.T, L.T panel & lighting conductor	Provided	MR			

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, it is recommended for renewal of fire safety certificate issued vide this department letter of even no. F.6/DFS/MS/2022/WZ/593 dated 28/12/2022.

Signature of the inspection Officer

Name:- C.L. Meena Designation:- ADO/Rohini Signature of the Inspecting Officer

Name:- A.K. Jaiswal Designation:- DO/NW

Principal Director

Princi