

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/SZ/2025/518

Dated: 3 / 10 /2025

To,

The Chief Architect, NDMC, Palika Kendra New Delhi.

Subject: - Regarding grant of Fire Safety Certificate in r/o Uttarakhand Niwas at Plot No.3, Gopinath Bardoli Marg, Chankya Puri, New Delhi - 110021.

Sir,

This has a reference to online ID. No NDMC/BP/0041/18-19 dated 13.09.2-25 on the subject cited above. In this connection, it is to inform you that premise was inspected by officers concerned of this department on 13/10/2025 in the presence of Sh.Bhagwan Singh Bisht & Sh. Pratap Singh (J.En.NDMC) and observed that building is comprised of 03 Basement, Ground + 06 upper floors upper floors. During the inspection the following shortcomings were observed:

- 1. Pressurization of staircases and lift well, lift lobby provided but found not functional.
- Smoke management systems provided but found not function in third basement and also not integrated with detection system.
- 3. MOEFA provided but found non-functional at some floors.
- 4. Exit signage not provided adequately at conspicuous place.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(A.K.Malik)

Dy. Chief Fire Officer

Delhi Fire Service

Copy to:-

1. The Authorized Signatory, Uttarakhand Niwas, Plot No.3, Gopinath Bardoli Marg, Chankya Puri, New Delhi - 110021.

41