C/38

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F.6/DFS/MS/CGHS/2025/SZ/ 1447

Dated: 20 / 08 /2025

To

Sh. Saurav Sisodia Singh Acting President, Vivekanand CGHS Ltd, Plot No. 02, Sector-5, Dwarka Phase-1, Near Madhu Vihar, New Delhi-110075

Sub: Regarding renewal of Fire Safety Certificate in r/o "Vivekanand CGHS Ltd" located at Plot No. 02, Sector-5, Dwarka Phase-1, Near Madhu Vihar, Delhi-110075

Sir,

This has reference to your letter No Nil dated 14/07/2025, received in this department vide outdoor diary No. 3791(A) dated 16/07/2025. In this connection, it is to inform you that the premise was re-visited by the officer concerned of this department on 25/07/2025 in the presence of Mr. Sumir Gupta (Hony. Secretary) to verify the compliance of shortcomings issued by this office vide letter No. F.6/DFS/MS/CGHS/2025/SZ/318 dated 02/07/2025 and observed that the shortcomings are still not complied.

In view of the above, application for renewal of fire safety certificate cannot be considered at this stage & rejected. The occupancy of premises in the absence of requisite fire protection measures shall be the sole responsibility & liability of the owner/occupier/management.

Yours faithfully,

(Virendra Singh) Chief Fire Officer Delhi Fire Service

Copy to: -

1. The Deputy Director (Bldg.), DDA, Vikas Sadan, INA, New Delhi-110023

Asr

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE CONNAUGHT PLACE: NEW DELHI-110001

No. F.6/DFS/MS/CGHS/2025/SZ/318

Dated: 02 /07/2025

To

The President/Secretary, Vivekanand CGHS Ltd, Plot No. 2, Sector-5, Dwarka, New Delhi-110075

Sub: Regarding issuance of Fire Safety Certificate in r/o Vivekanand CGHS Ltd located at Plot No. 2, Sector-5, Dwarka New Delhi.

Sir,

This has a reference to your letter No. Nil dated 01.06.2025 received in this department vide outdoor diary No. 2411 dated 04.06.2025, on the subject above. In this connection, it is to inform you that the premise was visited by the officer concerned of this department on 21/06/2025 in the presence of Mr. Saurabh Sisodia (Acting President) to verify the availability and operability of fire protections measures. During course of inspection, the shortcomings observed are as below.

- 1. Smoke exhaust system & automatic sprinkler system in basement found non-functional.
- 2. First aid hose reel system found non-functional.
- 3. Manually operated electrical fire alarm system found non-functional.
- 4. Internal hydrants found non-functional and some hose-boxes empty.
- 5. Terrace level fire pump found non-functional.

In view of the above, issuance of fire safety certificate is rejected. You are advised to rectify the above shortcomings at your earliest under intimation to this department in the interest of public safety.

Yours faithfully,

TUL G'ARG)
DIRECTOR

Ph. 011-23414000

Copy to: -

1. The Dy. Director (L&I), Building Section, Delhi Development Authority, Vikas Sadan, INA, New Delhi.