

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001



No F.6/DFS /MS/2025/WZ/ 596

Dated 06 /1) /2025

## FIRE SAFETY CERTIFICATE

Issued on ...0.6. 1.1.2025 at New Delhi by.

Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

 The Authorized Signatory, Vikas Surya Shopping Mall located at Plot No.18, Mangalam Place, District Centre, Sector-3, Rohini, Delhi-110085.

## Conditions for the validity of Fire Safety Certificate:

1. All the means of escape shall be kept free from any type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipment and method of smooth and speedy safe evacuation of occupants in case of emergency

3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seem during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities. This Fire Safety Certificate is valid only for permanent building structure as per plan.

5. This fire safety certificate may not be treated in any case of regularizations of unauthorized construction/unauthorized use of land or activities, if any.

6. Basement shall not be used for any other purpose except as specified in UBBL, subject to permission from concerned local authority.

7. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on the official website of Delhi Fire Service i.e. www.dfs.delhigovt.nic.in.

8. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J'

[sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

9. Banquet Hall/Eating House running in the said building shall obtain separate FSC/Renewal from this department.

## INSPECTION REPORT

1. Name & address of the building: Vikas Surya Shopping Mall, Plot No.18, Mangalam Place, District

Centre, Sector-3, Rohini, Delhi-85.

2. Type of Occupancy : Mercantile & Business

3. Type of Case : Renewal

4. Composition of building : Basement, Ground & 05 upper floors

5. Details of Previous FSC : F6/DFS/MS/2022/WZ/536 dated 29/11/2022
6. Fire Safety directives letter No : F6/DFS/MS/BP/2017/240 dated 04.08.2017

Date of inspection : 25/10/2025
 Name of Inspecting Officer : ADO (Rohini)

9. Name and designation of officers

From the building side : Mr. Tarun Sharma

10. Year of Construction : --

11. Applicant's letter No. : Online e-mail dated 12/08/2025

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBL/NBC Requirements	Provided at site	Remarks MR/NMR			
ι.	Access to building						
	Road width	6.0m	12.0m	MR			
	Gate width	Directly accessible	Directly accessible	MR			
	<ul> <li>Width of internal road</li> </ul>	NA	NA	NA			
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases	10	100				
	Upper Floors	06	Gr. to 1 <sup>st</sup> floor =10 Gr. to 2 <sup>nd</sup> floor =6 Gr. to 3 <sup>rd</sup> floor =5 Gr. to 5 <sup>th</sup> floor =2	MR			
	Basements	09	09	MR			
	b. Width of staircases						
	Upper Floor	Old case	Old case	MR			
	Basements	Old case	Old case	MR			
	c. Protection of exits						
	Fire check door	Required	Provided	MR			
	Pressurization	Required	Provided	MR			
	d. No. of continuous staircases to terrace	NA	NA	NA			
	e. Width of Corridor	NA	NA	NA			
	f. Door Size	Old case	Old case	MR			
3.	Compartmentation						
	Fire check door	Required	Provided	MR			
	<ul> <li>Sealing of electrical shafts</li> </ul>	Required	Provided	MR			
	<ul> <li>Fire Rating of shaft door</li> </ul>	Required	Provided	MR			
	Water Curtain	NA	NA	NA			
	Fire Dampers	NA	NA	NA			
4.	Smoke Management System						
	Basements	30 a/c per hour	Exhaust fan	MR			
	Upper floors	12 a/c per hour	Provided	MR			
5.	Fire Extinguishers						
	Total numbers	20nos.	28nos.	MR			
	Types	ABC/CO2	ABC/CO2	MR			
	IS marking	ISI marked	Yes	MR			

-1	N	147		
	First-Aid Hose Reels	24		
1	Total numbers on each floor	04	Provided	MR
- 1	<ul> <li>Length of hose reel hose</li> </ul>	30mm	Provided	M
-1	Nozzle diameter	5m	Provided	MR
-	Automatic fire detection and alarming system			/
	Type of detectors	Required	Provided	MR
	<ul> <li>Location of Main Panel</li> </ul>	Gr. floor	Provided	
	Location of Repeater Panel	NA	0.0000000000000000000000000000000000000	MR
	Alternate source of power	Required	NA Drawit 1	NA
	Hooters' Location	Required	Provided	MR
3	MOEFA	Required	Provided	MR
9. 10.	Public Address System	Required	Provided Provided	MR
IU.	Automatic Sprinkler System	required	Provided	MR
	Basement	Required	Degraided	
	Ground & Upper Floors	Required	Provided Provided	MR
11.	Sprinkler above false ceiling	Required	N. M. W. W. S. T. C.	MR
II.	Internal Hydrants	- soquitou	Provided	MR
	Size of riser/down-comer	06 mm	Provided	
	Number of hydrants per floor	04	Provided	MR
12.	Hose Box     Yard Hydrants	04	Provided	MR
			Tiovided	MR
	<ul><li>Total number of hydrants</li><li>Hose Box</li></ul>	09	Provided	1
13.	Pumping Arrangements	09	Provided	MR
	Ground Level		Trovided	MR
	<ul> <li>Discharge of main Pump</li> <li>Head of Main pump</li> </ul>	2850 LPM	Provided	MR
	Trade of Wall pump	60m	Provided	
	Trained of Hall pumps	02	Provided	MR
	Tamp out put	180 LPM	Provided	MR
	> Jockey pump head	60m	Provided	MR
	Standby Pump out put	2850 LPM	Provided	MR
	Standby Pump Head	60m	Provided	MR
	➤ Auto Starting/Manual Stopping ➤ Pump House Access	Required	Provided	MR
	- amp House Access	Required		MR
	Terrace level		Provided	MR
	Discharge of pump	NA	3.7.1	
	<ul><li>Head of the pump</li><li>Power Supply</li></ul>	NA	NA NA	NA
	> Auto Starting of pump	NA	NA NA	NA
14		NA	NA NA	NA
14.	Prive Water Storage for the lighting		A 1/4 A	NA
	Underground tank capacity	2,00,000 LTR	Provided	1.7-
	<ul> <li>Draw-off connection</li> <li>Fire service inlet</li> </ul>	NA	NA	MR
	Access to tank	NA	NA	NA
	Overhead Tank capacity	NA	NA	NA
4.6		20,000 LTR	Provided	NA
15	0 8	Required	Provided	MR MR
16	. Provision of Lifts.			IVIK
	Pressurization of Lift Shaft	NA	NA	
1	Pressurization of Lift lobby	Required	Provided	NA
	Communication In lift Car	Required	Provided	MR
	<ul> <li>Fireman's Grounding Switch</li> </ul>	Required	Provided	MR
	Lift Signage	Required	Provided	MR
			Provided	MR
17.	Standby power supply	Required	riovided	MR

a \*

> Total Area	NA	NA	NA	
> Location	NA	NA	NA	
Fire Control Room				
Detector System Panel	Required	Provided	MR	
Flow Switch Panel	NA	NA	NA	
PA System Panel	NA	NA	NA	
Battery backup	NA	NA	NA	
Building Floor Plans	NA	NA	NA	
Special Fire Protection System for Protection	NA	NA	NA	

The fire protection systems provided in the building were tested/ checked randomly and found in good

working condition, at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, it is recommended for renewal of fire safety certificate issued vide this

DO NW)

Dy. CFO (WZ)

Prince bal Director

ADO (lothini)

ADO (lothini)

ADO (lothini)

As approved, F.T. Letter is larup for year

Signature of the inspection Difficer
Name: - C.L. Meena
Designation:- ADO/Rohini

Dy. CFO (WZ)

Dy. CFO (WZ)

Prince bal Director

ADO (lothini)

AS approved, F.T. Letter is larup for year

Signature flease.

Dy efolloz)

F.P. Wing

06/11/2025

A DO (Rothini)