

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No. F6/DFS/MS/GH/NDZ/2025/ 482

Dated: 02 09 2025

## FIRE SAFETY CERTIFICATE (FSC)

Certified that the M/s VISA Guest House located at 9834-35, Gali No-6, Multani Dhanda, Pahar Ganj, New Delhi, building comprised of Ground + 02 upper floors: Ground floor - Reception, 1st floor to 2nd floor - 07 guest rooms each floor, and having two staff room at terrace floor, was granted Fire Safety Certificate (FSC) by this department vide letter no. F6/DFS/MS/GH/NDZ/2022/228 dated 17.05.2022. The Guest House was re-inspected by Officer concerned of this department on 25.08.2025 in presence of Mr. Manish (Manager) and found that Guest House has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the Guest House is fit for occupancy of Group 'A (Residential), sub division A-1, total 14 Guest Rooms (Ground floor - Reception, 1st floor to 2nd floor - 07 guest rooms each floor) with effect from .02.09 222and valid upto 31.03.2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on 02 09 2025 at New Delhi by

(Virendra Singh) Chief Fire Officer

of Dh

Reference: elt.mcdonline application no. 2025071511401.

Copy to-

1. The Commissioner, MCD, Dr. S.P.M. Civic Centre, Minto Road, New Delhi–110002:- To ensure the occupancy as detailed above.

## Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non functional f
- 3. ire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 8. The means of escape shall be kept unobstructed/unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

		INCDE	CTION PERCE				
1	Nar	ne & address of the building	CTION REPORT				
		of the building	Control S	House located at	Per Double Does Children		
2	Building is comprised of		No-6, Multani Dhanda, Pahar Ganj, New Delhi.  Ground + 02 upper floors  Ground floor - Reception				
			1st floor to 2nd fl	oor - 07 guest room			
	1	8		room at terrace and			
3	Tyr	pe of occupancy	as per undertaking Residential Sub D	submitted on dated	05.05.2022		
4	_	oe of case	Renewal	IVISIOII- A-1			
5	- 2			NDZ/2022/228 dated	17.05.2022		
	_	tails of previous FSC		NDZ/2022/228 dated	17.05.2022		
6		e safety directive letter no.	Nil				
7	Dat	te of inspection	25.08.2025				
8	Nai	me of the inspecting officers	Rajesh Kumar Shu	ıkla, ADO (M. Road	i)		
9		me of the designation of officer	Manager				
4.0		m the building side	2007				
10		ar of construction	2007		511101		
11		plicant's letter no.		lication no. 2025071			
S. No	1.46.00	nimum standard of Fire evention and Fire Safety U/R 33	Requirement as per Rule 35 (6)	Provide at site	Remarks MR/NM		
1	_	cess to Building	per Rule 33 (0)	Total Total	1,111,111		
	A	Road width	NA	2.0 m	NA		
	В	Gate width	NA	NA	NA		
- 14	C	Width of internal roads	NA	NA	NA		
2	Number, Width, Type & Arrangement of Exits						
	A	No. of staircase:	, ja .				
	Y.	a) Upper floor	1 no.	1 no.	MR		
		b) Basements	NA	NA	NA		
	В	Width of the staircase:	1	V - 10-10-12	f (		
		a) Upper floors	0.80 m	1.25 m	MR		
		b) Basements	NA	NA	NA		
	C	Protection of exits		T			
		a) Fire check door	NA	NA	NA		
	<b>D</b>	b) Pressurization  No. of continuous staircase to	NA NA	NA NA	NA		
	D	terrace:	NA .	NA	NA		
	E	Width of the corridor	1.25 m	1.40 m	MR		
	F	Door size	NA NA	0.80 m	MR		
3	Cor	npartmentation:			1		
	A	Fire check doors	NA -	NA	NA		
	В	Sealing of horizontal & vertical	NA	NA	NA		
		opening		7 1			
	C D	Fire rating of shaft doors Water curtain	NA NA	NA	NA		
	E	Fire dampers	NA NA	NA NA	NA		
5		oke Management System:	1 * 14 *	LANCA 1	NA		
	A	Basements	NA	NA	NA		
	В	Upper floors	Required	Provided	MR		
	Fire	e Extinguishers		11 11 11 11	A		
	A	Total numbers	09 nos.	09 nos.	MR		
	В	Types	CO <sub>2</sub> , ABC	CO <sub>2</sub> , ABC	MR		
		ISI marking	Required	Provided	MR		

H	12

6	A	rst Aid Hose Reel Total no. at each floor	l no.	l no.	MR		
	B		30 m	30 m	MR		
	C		5 mm	5 mm	MR		
7	Au	tomatic Fire Detection and Alarm S	ystem (ADAS)	(Required as p			
	7.31.viii, UBBL 2016).						
	A	1 ) 50 0. 2010	CO detector	Provided	MR		
	В	Location of main Panel	Ground	Provided	MR		
	C	Location of repeater panel	NA NA	NA NA	NA		
	D	Alternate power source	Audible in	Provided	NA		
	E	Hooter's location	entire building	Flovided	MR		
•	341	DEFA	NA NA	NA	NA		
9	2000	blic Address System	Required	Provided	MR		
10	Au	tomatic Sprinkler System	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		IVIIC		
10	Au	Basement	NA	NA	NA		
	B	Upper floor-	NA	NA	NA		
	C	Sprinklers above false ceiling	NA	NA	NA		
11	1000	ernal hydrants			1 2 2		
	A	Size of the riser/down comer	NA _	NA	NA		
	B	No. of hydrants per floor	NA	NA	NA		
	C	Hose box	NA	NA	NA		
12	Yard Hydrants						
17000	A	Total no. of hydrants	NA	NA	NA		
	В	Hose box	NA	NA	NA		
13	Pu	mping arrangements					
	A	Ground Level					
		a) Discharge & head of main	NA	NA	NA		
		pump					
		b) Number of main pump	NA	NA	NA		
		c) Discharge & head of jockey	NA	NA	NA		
		pump		2 5			
		d) Discharge & head of Standby	NA	NA	NA		
		pump					
	10.0	e) Auto starting/ manual stopping	NA	NA	NA		
	B Terrace Level						
	_	a) Discharge of terrace	450 LPM	Provided	MR		
		pump					
		b) Head of terrace pump	30 m	Provided	MR		
		c) Alternate power supply	Required	Provided	MR		
		d) Auto starting of pump	Required	Provided	MR		
	_	ptive Water Storage for Fire Fig					
14			NA	NA	NA		
	A	Underground tank capacity	NA NA	NA	NA		
	В	Draw off connection		NA NA	NA		
	C	Fire Service Inlet	NA	NA NA	NA		
	E	Access to tank	NA	Provided	MR		
	D	Overhead tank capacity	2,500 ltrs	Provided	MR		
15	Ex	it Signage	Required	Provided	- PA-S		
16	Dravisian of lift						
10	A	Pressurization of lift shaft	NA	NA	NA NA		
	15/161	Pressurization of lift lobby	NA	NA	NA NA		
	B		NA	NA	NA NA		
	C	Communication in lift car	NA NA	NA			
	D	Fireman switch		NA	NA NA		
	E	Lift signage	NA	Provided	MF		

18	Refuge Area				
	A	location	NA	NA	NA
	В	Total area	NA	NA	NA
19					
	A	Fire Detection System panel	NA	NA	NA
	В	Flow switch panel	NA	NA	NA
	-		NA	NA	NA
	C	P A system panel	NA	NA	NA
1	D	Battery backup		NA	NA
	E	Building floor plan	NA	107	
20	Special Fire Protection for special risk if any				
	A Special Fire Protection for Special Risk, if any:				

## LEGENDS:-Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

The shortcomings issued to the Guest House by this department vide letter no.F6/DFS/MS/GH/NDZ/2025/320 dated 11.07.2025 has been rectified by the

management.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2022/228 dated 17.05.2022 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name: Rajesh Kumar Shukla
Designation: ADO (M. Road)

DO(CD)

298/25

Dycholoroz)

C.F.O.

Principal Director

Cro to Jam

D) 29/18

Prie but up 1

cro/ 29/8/2015

ms land