GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/Business/2025/SZ/ 508

Dated: 22 09 2025

FIRE SAFETY CERTIFICATE

Certified that the Vishal Tower located at Plot No. 10, District Centre, JanakPuri, New Delhi-110058, comprised of basement, ground floor, upper ground & eleven upper floors owned/occupied by Ajay Enterprises Pvt. Ltd., was issued FSC by this department vide letter No. F.6/DFS/MS/Business/2022/SZ/447 dated 07.10.2022. The building was re-inspected by the officer concerned of this department on dated 15.09.2025 in the presence of Mr. Arvind Saxena (G.M. Estates), and found that the building management have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class "Business Building" w.e.f. 2209 2010 and valid up-to 31.03.2028, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 22 09 2025 at New Delhi by.

(Virendra Singh) Chief Fire Officer

Copy to: -

1. The G.M Estate, Vishal Tower at Plot No. 10, District Centre, Janakpuri, New Delhi- 110058.

2. The Commissioner, MCD, Delhi: for information regarding use of basement with a request to ensure the occupancy as detailed above and deviation, if any.

Conditions for the validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building

Vishal Tower, Plot No. 10, District Centre, Janak Puri, New

2. Building comprised of

Basement, ground floor, upper ground & eleven upper floors.

3. Type of Occupancy

Mixed (Mercantile & Business)

4. Type of Case

Renewal

5. Details of Previous NOC

F.6/DFS/MS/ Business/2022/SZ/447 dated 07.10.2022

6. Fire Safety directives letter No

F6/DFS/MS/86/146 dated 10/02/1987

7. Date of inspection

15.09.2025

8. Name of Inspecting Officers

A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side

Sh. Arvind Saxena (G.M Estates)

10. Year of Construction

1990-91 :

11. Applicant's letter No.

Nil dated 09.09.2025

Sr. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NM			
•	Access to building		1				
	Road width	Accessible	06 m	MR			
	Gate width	Required	Directly approachable	MR			
	Width of internal road	N/A	N/A	N/A			
•	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases			I			
	Upper Floors	Three	Provided	MR			
	Basements	Two & ramp	Provided	MR			
	b. Width of staircases	1 wo at ramp	Tiovided	IVIK			
	Upper Floor	2x1.20 &.90 m	Provided	MR			
	Basements	1.30 m, 1.0 m & 2.76 m ramp	Provided	MR			
	c. Protection of exits						
	Fire check door	Required	Provided	MR			
	Pressurization	N/A	N/A	N/A			
	d. No. of continuous staircases to	1771	10/14	11/11			
	terrace	Three	Provided	MR			
	e. Width of Corridor	N/A	N/A	N/A			
	f. Door Size	1.0 m	1.0 m	MR			
3.	Compartmentation						
	Fire check door	Required	Provided	MR			
	 Sealing of electrical shafts 	Required	Provided	MR			
	Fire Rating of shaft door	02 hrs.	Provided	MR			
	Water Curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
i.	Smoke Management System						
	Basements	Required	Provided	MR			
	Upper floors	Required	Natural ventilation provided	MR			
5.		Required					
	Fire Extinguishers						
	 Total numbers 	04 no.'s at each floor	Provided	MR			
	• Types	W/CO ₂ / CO ₂ /ABC type	Provided	MR			
	• IS marking	ISI marked	Provided	MR			

	First-Aid Hose Reels						

	Total numbers on each floor	One		MR			
	• Length of hose reel hose	30 m	Provided Provided	MR			
	Nozzle diameter		Provided	MR			
•	Automatic fire detection and alarming	5 mm	1 Tovided				
	1 Vmo of 1.4						
	Location of Main Panel	Required smoke & heat	Provided	MR MR			
	Location of Repeater Panel	Required	G. Floor	N/A			
	Alternate source of power	N/A	N/A	MR			
	Hooters' Location	Required	Provided	MR			
		Required	Provided				
3.	MOEFA	Required	Provided	MR			
),	Public Address System	Required	Provided	MR			
0.	Automatic Sprinkler System						
	Basement	Required	Provided	MR			
	Upper Floor	Required	Provided	MR			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
11.		150 MM	Provided	MR			
	Size of riser/down-comer	One	Provided	MR			
	Number of hydrants per floor Hass Poy	One	Provided	MR			
	Hose Box						
12.	Yard Hydrants		Provided	MR			
	Total number of hydrants	4 Nos.	Four	MR			
	Hose Box	Required	Four	1/110			
13.	Pumping Arrangements						
13.	Ground Level		Provided	MR			
	Discharge of main Pump	2400 LPM	Provided	MR			
	▶ Head of Main pump	70 m	Provided	MR			
	Number of main pumps	Two	Provided	MR			
	▶ Iockey Pump out put	180 LPM 40 m	Provided	MR			
	> Jockey pump head	2400 LPM	Provided	MR			
	> Standby Pump out put > Standby Pump Head	70 m	Provided	MR			
	Ctarting/Manual	Required	Provided	MR			
	Stopping	50	Provided	MR			
	> Pump House Access	Required	Tiovided	MIK			
	• Terrace level	N/A	N/A	N/A			
	> Discharge of pump	N/A N/A	N/A	N/A			
	> Head of the pump	N/A	N/A	N/A			
	Power Supply	N/A	N/A	N/A			
	> Auto Starting of pump						
14	Captive Water Storage for fire fighting		- D				
14.	Underground tank capacity	2,50,000 ltrs	Provided	MR			
	off connection	Required	Provided Provided	MR			
142	Fire service inlet	Required	Provided	MR			
	Access to tank	Required	Provided	MR			
	Overhead Tank capacity	50,000 Ltrs	Provided	MR			
	Exit Signage. Required Provided			MR			

16.	Pressurization of Lift Shaft	N/A	N/A		
	 Pressurization of Lift lobby 	N/A	A A PLANTED	N/A	
	 Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply	Required	N/A	N/A	
		Required	Provided	MR	
		Required	Provided	MR	
		Required	Provided	MR	
17.	Standay power suppry		Provided	MR	
	> Total Area > Location	19.64, 26.85 & 37.65sq.	Provided	MR	
	The state of the s	19.64, 26.85 & 37.65sg	Provided		
		4 th 6 th &9 th Floor	Provided	MR	
	Fire Control Room				
9.	Fire Control Room	X.			
9.	Detector System Panel	Required	Provided	MR	
9.	Detector System Panel Flow Switch Panel	Required N/A	Provided N/A	MR N/A	
9.	 Detector System Panel Flow Switch Panel PA System Panel 			N/A	
9.	 Detector System Panel Flow Switch Panel PA System Panel Battery backup 	N/A	N/A	N/A MR	
9.	 Detector System Panel Flow Switch Panel PA System Panel Battery backup 	N/A Required	N/A Provided	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter No. F.6/DFS/MS/Business/2022/SZ/447 dated 07.10.2022, is recommended to be renewed under rule 37, of the Delhi Fire Service Rules, 2010.

Signature of the Inspecting Officer Name: - R.K. Yadav

Designation: - ADO (JKP)