0. F6/DFS/MS/GH/NDZ/2025/ 418

Dated: 23/06/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s You and Me Guest House located at 4459 - 4462, Katra Rai Ji, Pahar Ganj, New Delhi - 110055, building comprised of ground plus four upper floors, Ground floor (Reception + Office), 1st floor to 3rd floor (05 guest rooms at each floor), 4th floor (05 guest rooms not in use), total 15 guest rooms owned / occupied by You and Me was granted FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2022/220 dated 12/05/2022 for 15 rooms. The premises was re-inspected by the officer concerned of this department on 12/06/2025 in the presence of Mr. Martujali (Manager) and found that the said guest house building having given an affidavit dated 12.06.2025 regarding not to use any floor above third floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group - A "Residential Building" Sub Division-A-1, as above Ground floor (Reception + Office), 1st floor to 3rd floor (05 guest rooms at each floor) total 15 guest rooms only with effect from <u>23</u>/06/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010. Subject to conditions printed below.

at New Delhi by.

Copy to: -

- 1. The Commission, MCD Civic Center, New Delhi: to ensure the occupancy as detailed above.
- 2. The Joint Commissioner of Police (Lic.), first Floor, Police Station Defence Colony, New Delhi 110024. w.r.t.- MCD portal ID - 2025060109443 dated 01/06/2025.
- 3. The Manager, You and Me Guest House at 4459-4462, Katra Rai Ji, Pahar Ganj, New Delhi 110055.

Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. The trained firefighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

		_	HAN ARREST CONT.	NSPECTION DE	Pos			
1	Name	& &	address of the building	NSPECTION RE	CPORT			
				TOU & ME (fliest Lieur)				
2 1	Building is comprised of			Ground + 04 upper floors (total 15 G				
					CUIIIIII + I Ittical 19 G	and a		
71								
				rooms at each floor) and 4th floor not in use as per affidavit dated 12/06/2025 regarding not to use any floor above third floor.				
3	Туре	of o	ccupancy					
4	Type of case Residential, Sub Division-A-1							
			previous FSC	Renewal				
6	Fire	afet	brevious FSC	F6/DFS/MS/GH/NDZ/2022/220 dated 12/05/2022				
7	Data	ot.	y direction letter no.	N/A				
	Date of inspection							
0	Name of the inspecting officers				Meena, A.D.O / Laxmi]	Vagar		
9	Nam	e of	the designation of	Mr. Martuiali (M	anager)	vagai		
	officer from the building side			Mr. Martujali (Manager)				
10	Year of construction			1982				
			's letter no					
T'-	AR TET THE			MCD Portal application No. 2025060109443 dated 01/06/2025				
- June	N	/lini	mum Standards on	Requirement	Remarks			
S.No	o fire Prevention and fire			Existing fire safe	ety Provided at Site			
	safety requirements U/R 33		requirements U/R 33	arrangements				
1	Access to building		to building		B= 計 < /	304		
	a	a Road widthb Gate width		N/A	6.0 meters	N/A		
	b			N/A	N/A	N/A		
	c	1.1.1.1	idth of internal road	N/A	N/A	N/A		
2	Nu	mbe	r, Width, Type and Ai	rrangement of Exi	its	Large Land		
	A	N	Number of staircases		Statement down			
		a	Upper floor	01 no.	01 no.	MR		
= 4		b	Basement	N/A	N/A	N/A		
	В		Width of staircases	TE SEVEN				
	- 51.°	a	Upper floor	1.50 meter	1.30 meter to 1.50	MR		
7	1				- meters			
		b	Basement	N/A	N/A	N/A		
2.1	C	Pr	otection of exits	uses of R	Committee of the second			
		a	Fire check door	N/A	N/A	N/A		
		b	Pressurization	N/A	N/A	N/A		
	D N		o. of continuous	01 no.	01 no.	MR		
50		_	ircases to terrace			IVIK		
	E	_	dth of corridor	N/A	N/A	N/A		
	F Door size			1.0 meter	1.0 meter	MR		
3	Compartmentation			man L'				
	a			N/A N/A		NT/A		
	b	B or oroditour straits		N/A	N/A	N/A		
	c	8 511411 4001		N/A	N/A	N/A		
	d Water curtain		DATE TO SECURE OF THE PARTY OF	N/A N/A		N/A		
	e Fire dampers			N/A	N/A	N/A		
4	Smoke Management System			N/A N/A				
	a Basement			N/A	N/A	2720		
	b Upper floor			12 ACPH	Natural/Exhaust fan	N/A		
					- Manager Lan	MR		

Natural/Exhaust fan

MR

N/26 M/s You & Me Guest House located at 4459-4462, Katra Rai Ji, Pahar Ganj, New Delhi - 110055

	Fire Extinguisher 10 nos.							
			al numbers	10 nos.	CO ₂ & ABC	MR		
ŀ	b	Тур	oes	CO ₂ & ABC	ISI marked	MR		
	440		marking	ISI marked	ISI marked	• • • • • • • • • • • • • • • • • • • •		
	Ti 4 ald Hose Deels					MR		
6	land have of each floor			01 no.	01 no.	MR		
	a	100	ngth of hose reel hose	30 mtrs	30 mtrs			
	b			05 mm	05 mm	MR		
	c Nozzle diameter Automatic Fire Detection & Alarm			ing System.				
7	A	uton	natic Fire Detection & Alarm	Required	Provided	MR		
	a	T	ype of detectors CO Type	Ground floor	Provided	MR		
	b	L	ocation of main panel	N/A	N/A	N/A		
	c	L	ocation of repeater panel	Required	Provided	MR		
	d	A	Iternate source of power	Each floor	Provided	MR		
	e		looter's location	N/A	N/A	N/A		
8		ЮE		N/A	N/A	N/A		
9	P	ubli	c Address System.	****		- 1		
10	A	_	natic Sprinkler System.	N/A	N/A	N/A		
Ly.	a		sement	N/A	N/A	N/A		
	b	U	oper floors		N/A	N/A		
	c Sprinkler above false ceiling							
11	Internal Hydrants			NT/A	N/A	N/A		
	a	a Size of riser/down-comer		N/A N/A	N/A	N/A		
	b			N/A	N/A	N/A		
10	c	c Hose Box		IN/A		-		
12	Yard Hydrants.			N/A	N/A	N/A		
	a	a Total number of hydrants		N/A	N/A	N/A		
di		b Hose Box		N/A	1772			
13	Pumping Arrangements.							
	A		Ground Level	N/A	N/A	N/A		
	-	a	Discharge of main Pump	N/A	N/A	N/A		
		b	Head of Main Pump	N/A	N/A	N/A		
	1	c	Number of main pumps	N/A N/A	N/A	N/A		
	1	d	Jockey pump out put	N/A	N/A	N/A		
		e	Jockey pump head	N/A N/A	N/A	N/A		
	-	f	Stand by pump out put	N/A	N/A	N/A		
	-	g	Stand by pump head Auto starting /manual	N/A	N/A	N/A		
		h	E	13/21	DINOC TESTAS E TANGE			
	B Terrace Level							
	The state of the s					100		
		a	Discharge of pump	450 LPM	450 LPM	MR		
		b	Head of the Pump	30 mtrs.	30 mtrs.	MR		
	_	c	Power supply	Required	Provided	MR		
, A.		d	Auto Starting of pump	Required	Provided	MR		

14	Trace Storage for Fire Fig. 1						
	a	Underground tank capacity					
	b	Draw-off connection	N/A	N/A	N/A		
	c		N/A	N/A	N/A		
		Fire service inlet	N/A	N/A	N/A		
	d	Access to tank	N/A	N/A	N/A		
	e	Overhead Tank capacity	5000 liters.	5000 liters.	MR		
15,	E	xit Signage.	Required	Provided	MR		
16	Provision of Lifts						
	a	Pressurization of Lift Shaft	NA	NA	, NA		
	b	Pressurization of Lift lobby	NA	NA	NA		
	c	Communication in lift car	NA	NA	NA		
	d	Firemen's switch	NA	NA	NA		
	e	Lift Signage	NA	NA	NA MR		
17	1	andby power supply	Required	Provided	MIK		
18	Defuge Area						
10	+	Total area	NA NA	NA	NA NA		
	a b	Location	NA	NA	MA		
19	Ti C t I Pear						
17	-	Detector system panel	N/A	N/A	N/A N/A		
	a b	Flow switch panel	N/A	N/A N/A	N/A		
	_	PA system panel	N/A	N/A N/A	N/A		
	d	Battery backup	N/A	N/A	N/A		
	e Building Floor Plans		N/A	I Risks. if	N/A		
20	e Building Floor Plans Special Fire Protection systems for protection of special Risks, if						
20	any: (i) that the Ground floor (Reception + Office),						

NOTE: - At the time of inspection that the Ground floor (Reception + Office), 1st floor to 3rd floor (05 guest rooms at each floor) and 4th floor not in use as per affidavit dated 12/06/2025 regarding not to use any floor above third floor (Affidavit pleased at C/79).

The fire protection system was randomly checked and tested and was found functional at the time of inspection. The shortcomings issued by this department vide letter no. F6/DFS/MS/GH/2025/246 dated 21/05/2025 have been rectified.

Keeping in view the compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2022/220 dated 12/05/2022 renewal under rule 35(6) of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer Name: Yashwant Singh Meena Designation: ADO/Laxmi Nagar

OJCD SA

> 6/6/25 .

Liv P