

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/2025/EH/ 504

Dated 19 /09/2025

#### FIRE SAFETY CERTIFICATE

Certified that the M/s Zamaya and Amare (A Unit of Lively Bites and Entertainment Pvt. Ltd) located at Third Floor, Plot No-81, Adchini, Sri Aurobindo Marg, Delhi-110017 in a building comprised of basement, ground & 03 upper floors owned/occupied by M/s Zamaya and Amare (A Unit of Lively Bites and Entertainment Pvt. Ltd) have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 13/09/2025 in the presence of Sh. Manish Sharma and that the building/ premise is fit for occupancy Class "Assembly (Restaurant) at third floor only" with effect from 19/69/262 for a period of three years, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 19/09/2025 at New Delhi by

Virendra Singh Chief Fire Officer Delhi Fire Service

#### Copy to: -

- 1. The Commissioner, Municipal Corporation of Delhi, with a request to ensure the occupancy as detailed above deviation and if any. Online ID No- 2025090213120 dated: 03.09.2024 & 2025090913314 dated 09/09/2025.
- M/s Zamaya and Amare (A Unit of Lively Bites and Entertainment Pvt. Ltd) located at Third Floor, Plot No-81, Adchini, Sri Aurobindo Marg, Delhi-110017.

### Conditions for the validity of Fire Safety Certificate:

- 1. This Fire Safety Certificate is valid only for restaurant at third floor. In case of any violation, this FSC will be treated as null & void.
- 2. All the means of escape shall be kept free from any type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment and method of smooth and speedy safe evacuation of occupants in case of emergency
- 4. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seem during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 5. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities. This Fire Safety Certificate is valid only

  6. This fire of the fire of the concerned authorities.
- 6. This fire safety certificate may not be treated in any case of regularizations of unauthorized construction/unauthorized use of land or activities, if any.
- 8. The owner / occupier shall submit a declaration every year in Form "K" provided in the first Schedule of Delhi Fire Service Rules 2010. The form is available on the official website of "The owner of the company of
- 9. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the MCD Portal along with a copy of this Certificate, six months prior to its expiry".

# INSPECTION REPORT

1. Name & address of the building

: M/s Zamaya and Amare (A Unit of Lively Bites and Entertainment Pvt. Ltd)

At Plot No-81, 3rd floor, Adchini, Sri Aurobindo Marg, Delhi-110017.

2. Type of Occupancy

: Assembly (Restaurant)

3. Type of Case

: New Case

Composition of building

: Basement, Ground & 03 upper floors, But (Restaurant proposed at 3rd floor

Only),

5. Details of previous NOC

: Nil

Fire Safety directives letter No

: Nil

7. Date of inspection

: 13/09/2025

Name of the Inspecting Officers 8.

: ADO (RN)

Name and designation of officers

from the building side

: Sh. Manish Sharma

10. Year of Construction

: 1991 as per online MCD portal detail

	2025090913314 dated 09/09/2025							
	Minimum Standards on fire prevention and fire safety U/R 33	NBC Part-IV/UBBI Requirements	Provided at site	Remarks MR/NMR				
1	Access to building							
	Road width	06m	06m	MR				
	Gate width	NA	NA	NA				
	Width of internal road	NA	NA	NA				
2	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases		7,					
	Upper Floors	02	03	MR				
	Basements	NA	NA	NA				
	b. Width of staircases							
	• Upper Floors	02m	03 nos. of s/c is 02m, 1.90 to 02m & 1.15 to 1.90m	MR				
	Basements	NA	NA ·	NA				
	c. Protection of exits							
	Fire check door	Required	Provided	MR				
	<ul> <li>Pressurization</li> </ul>			1404000000 I				
	d. No. of continuous staircases to terrace	NA	NA	NA				
	e. Width of Corridor	02 NA	02	MR				
	f. Door Size	02m	NA Provided	NA MR				
3	Compartmentation.							
	Fire check door	NA	NA	NA				
	Sealing of electrical shafts	NA	NA NA	NA				
	Fire Rating of shaft door	NA	NA	NA				
	Water Curtain	NA	NA	NA				
	Fire Dampers	NA	NA	NA				
	Smoke Management System.							
	Basements	NA	NA	NA				
	Upper floors	Required	Natural Ventilation	MR				
	Fire Extinguishers							
	Total numbers	04nos	05nos	MR				
	Types	ABC/Co2	ABC-5	MR				
	ISI marking	Yes						
	Participation of the second of	1 68	Provided	MR				

5	First-Aid Hose Reels.				
	Total numbers on each fioor	01	Provided		
	<ul> <li>Length of hose reel hose</li> </ul>	30m	Provided	M	
	Nozzle diameter	5mm	Provided	M	
7	Automatic fire detection and alarming system.				
	Type of detectors     Smoke/Heat Provided				
	Location of Main Panel	Third floor		M	
	Location of Repeater Panel		Provided	MI	
	The state of the s	NA	NA	N/	
	Alternate source of power	Required	Provided	MF	
8	Hooters' Location	Required	Provided		
9	MOEFA	Required	Provided	MR	
10	Public Address System.	NA	NA	MR	
10	Automatic Sprinkler System.			NA	
	Basement	NA	NA		
	Upper Floor	NA	Provided	NA	
	<ul> <li>Sprinkler above false ceiling</li> </ul>	MODEL		NA	
11	Internal Hydrants	NA	NA	NA	
	<ul> <li>Size of riser/down-comer</li> </ul>	100mm			
	Number of hydrants per floor	01	Provided	MR	
	Hose Box	01	Provided	MR	
12	Yard Hydrants.	01	Provided	MR	
	Total number of hydrants				
	Hose Box	NA	NA	NA	
13	Pumping Arrangements.	NA	NA	NA	
	Ground Level				
	Discharge of main Pump			-	
	Head of Main pump	2280 LPM	Provided	MD	
	Number of main pumps	70m	Provided	MR MR	
	> Jockey Pump out put	01nos	Provided	MR	
	➤ Jockey pump head	180 LPM	Provided	MR	
	Standby Pump out put	70m	Provided	MR	
	<ul><li>Standby Pump Head</li></ul>	2280 LPM (D.G. Set)	Provided	MR	
	Auto Starting/ Manual stopping	70m Required	Provided	MR	
	Pump House Access	Required	Provided Provided	MR MR	
	Terrace level				
	Discharge of pump	450 LPM	Provided	Mb	
	➤ Head of the pump	40m	Provided	MR	
	Power Supply  Auto Starting of automatical starting of	Required	Provided	MR MR	
14	rate starting of pump	Required	Provided	MR	
1421	Captive Water Storage for fire fighting.				
	Underground tank capacity	1,00,000 LTR	Provided	MR	
	Draw-off connection	NA	NA	NA NA	
	<ul><li>Fire service inlet</li><li>Access to tank</li></ul>	NA	NA NA	NA NA	
	Overhead Tank capacity	Required	Provided	MR	
15	Exit Signage.	5,000 LTR	Provided	MR	
	. БР	Required		WIIX	



16	Provision of Lifts.					
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul>	N/A N/A				
		N/A	N/A	N/A		
		NA NA	N/A	N/A		
			NA	NA		
		Required	Provided	MR		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.	Required	Provided	MR		
	> Total Area					
	> Location	N/A	N/A	N/A		
19	Fire Control Room	N/A	N/A	N/A		
	The Control Room					
	<ul> <li>Detector System Panel</li> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Batter backup</li> </ul>	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
0	Building Floor Plans	N/A	N/A	N/A		
0	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA		

The fire protection systems provided in the building were tested/ checked and found in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended for Grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name:- C.L. Meena

Designation:- Asst. Div. Officer (RN)

Mukesh Verma (DO/South)

Muly 15/8/26

17/91/2025

Principal Director

Pro

to Jan

OF0

7

18 tal sax

T letter is farup for your

CFO

My \_

Signature Plane.

18 09 2025

Ms

1. Blom ded